

**Adjustment of Spare Parts Costs for Repairs SJN 3226D
HONDA AIRWAVE**

Item	Qty	Vehicle parts description	Estimate by workshop
List Items			
1	1	rear bumper	\$680.00 <i>de</i>
2	2	rear bumper side retainer	\$55.00 <i>Xnn</i>
3	2	rear bumper bracket	\$44.00 <i>Xnn</i>
4	1 set	rear bumper clips	\$35.00 <i>300</i>
5	2	tail lamp LH & RH	\$720.00 <i>2HXnn RHnn / 360</i>
6	2 sets	tail lamp clips	\$42.00 <i>Knn</i>
7	1	tail gate	\$1,030.00 <i>bt</i>
8	1	tail gate inner lock	\$165.00 <i>bt</i>
9	1	tail gate lock striker	\$35.00 <i>Xnn</i>
10	1	tail gate wiper arm	\$60.00 <i>ant</i>
11	1	tail gate wiper blade	\$55.00 <i>ant Xnn</i>
12	1	tail gate wiper motor	\$288.00 <i>Xnn</i>
13	1	tail gate weatherstrip	\$185.00 <i>? ant</i>
14	1	tail gate honda logo	\$80.00 <i>rec 53</i>
15	1	tail gate airwave logo	\$85.00 <i>wh 48</i>
16	2	tail gate shock absorber LH & RH	\$300.00 <i>Xnn</i>
17	1	tail gate stopper	\$10.20 <i>rec</i>
18	1	tail gate inner trim board	\$220.00 <i>de</i>
19	1	tail gate lower pull handle	\$55.00 <i>Xnn</i>
20	1	tailgate center chrome garnish	\$185.00 <i>ant</i>
20	1	tail gate centre garnish	\$125.00 <i>de</i>
21	2	tail gate lamp LH & RH	\$580.00 <i>2HXnn RHnn 290</i>
22	2	tail gate car plate lamp LH & RH	\$110.00 <i>Xnn</i>
23	1	rear end panel	\$355.00 <i>Rx</i>
24	1	rear end panel top garnish	\$155.00 <i>de</i>
25	1	rear end panel top garnish clips	\$20.00 <i>rec</i>
26	1	rear spare tyre panel	\$680.00 <i>Xnn</i>
27	1	rear spare tyre panel board	\$400.00 <i>Xnn</i>
28	2	rear windscreen glass moulding	\$105.00 <i>wa</i>
29	2	rear wind screen inner seal	\$55.00 <i>wa</i>
30	1	rear windscreen	\$980.00 <i>Xnn</i>
31	1	rear exhaust muffler	\$680.00 <i>Xnn</i>
32	1	rear fender inner trim LH & RH	\$600.00 <i>LHnn RHnn 300</i>
33	2 set	rear fender inner trim clips LH & RH	\$48.00 <i>Xnn</i>

\$9,222.20

4096.20
20% - 3276.96

Less 20%

\$1,844.44

\$7,377.76

Special nett item

- | | | |
|---|---|-------------------------------|
| 1 | 1 | windscreen sealant |
| 2 | 1 | rear end panel sealant |
| 3 | 1 | rear spare tyre panel sealant |
| 4 | 1 | reverse camera |
| 5 | 4 | reverse sensor |
| 6 | 2 | number plate w casing |

Total parts

\$60.00 *104*
\$60.00 *140Xun*
\$60.00 *Xun*
\$250.00 *2un*
\$200.00 *un*
\$50.00 *45 305*
\$680.00

Adjustment of Labour Costs for Repairs

Spraying of affected areas

\$800.00 *700*

Carry out body cavity preservation

\$100.00 *30*

To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat

\$1,000.00 *700*

Check wiring

\$50.00 *30*

Remove & reinstall rear windscreen

\$120.00 *R ✓*

Remove & refix bootlid componets

\$80.00 *60*

Remove & reinstall reverse sensor

\$80.00 *30*

Remove & reinstall rear boot upholstery

\$100.00 *60*

Total labour

\$2,330.00 *1730*

Taufik 97415445

'WP' 20/12/21 @ 1400

1/5 Resurvey after repair

taufik@lkkauto.com

3296.96 6 days

305

1730

5311.96

4/5 \$4200 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: