

MSIAO Zang

Not Authorized

17/12/21

2/s# 3300/

3 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: GBF 569X

1PC	SLIDING DOOR N/S	100/3000	1545.10	\$1,655.10
1PC	SLIDING DOOR INNER LOCK N/S	11		\$425.80 X
1PC	REAR FENDER N/S	12		\$1,971.10 X
1PC	REAR FENDER RAILING N/S	11		\$366.50 X
1PC	REAR WHEEL HUB CAP N/S	woped	160.00	\$198.00
1PC	REAR WHEEL HUB BEARING N/S	Damaged	545.10	\$650.00
1PC	REAR WHEEL HUB SHAFT N/S	Damaged		\$725.10
1PC	REAR BUMPER	cut	631.10	\$685.20
1PC	REAR BUMPER SIDE RETAINER N/S	11		\$105.00
1SET	REAR BUMPER CLIPS	11		\$50.00
1PC	TAILLAMP N/S	11		\$398.20 X
				\$7,230.00

TO TRANSFER SLIDING DOOR N/S

\$80.00 50

TO SPRAY RUST PROOFING

\$80.00 50

TO CONDUCT WHEEL ALIGNMENT

\$120.00 80

TO DISMANTLE & REPLACED REAR WHEEL HUB BEARING

\$180.00 150

LABOUR FOR PANEL BEATING & REPLACED PARTS

\$980.00 600

TO PUTTY & SPRAY PAINTING

\$900.00 500

TOTAL \$9,570.00

p. 3761.40

50%

p. 1880.70

L-1430

3310.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: