

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG21012783/GVCE2**Date:** 11/04/2022**REFERENCE**

Insured/Claimant:	YEO YIAN CHONG	Policy No:	7210105665
Date of Loss:	11/12/2021	Nature of Claim:	OD
		Claim No:	3538101436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP9198B	Engine No:	DGK006934
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Chassis No:	WAUZZZF7M2101820
Reg. Date:	31/08/2021 (Man. Year: 2021)	Odometer:	6217 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$256,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,516.00	2,350.40	6,165.60	72.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,672.00	3,832.00	2,840.00	42.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,188.00	6,182.40	9,005.60	59.29
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	14,688.00	5,682.40	9,005.60	61.31
+ GST 7.00/7.00% (S\$)	1,028.16	397.77	630.39	61.31
Nett Amount (S\$)	15,716.16	6,080.17	9,635.99	61.31

INSPECTION

Date of Assignment:	17/12/2021		
Date Inspected:	16/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,405.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Not Necessary	913.00 FS	*- FS
3	1		*REAR BUMPER LOWER COVER - RH	Not Necessary	261.00 FS	*- FS
4	1		*REAR BUMPER CLOSING ELEMENT - RH	Not Necessary	300.00 FS	*- FS
5	1		*REAR BUMPER TOWING EYE COVER - RH	Not Necessary	121.00 FS	*- FS
6	1		*REAR BUMPER TRIM INNER / OUTER - RH	Outer Cut	458.00 FS	*366.40 FS
7	1		*TAIL LIGHT - RH	Not Necessary	699.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	106.00 FS	*- FS
9	2		*REAR WHEEL ARCH COVER - LH / RH	Missing	1,166.00 FS	*932.80 FS
10	1		*ALUMINIUM RIM	Cut	1,314.00 FS	*1,051.20 FS
11	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	278.00 FS	*- FS
12	1		*RHS REAR TYRE (NPA)	Not Necessary	0.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
14	1		*REAR PARKING AID SENSOR SUPPORT OUTER - RH	Not Necessary	95.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **8,516.00** **2,350.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	750.00
3	TO RENEW RHS REAR RIM AND TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO RESPRAY REAR BUMPER, RHS REAR BUMPER COVER, RHS REAR FENDER, BOTH REAR WHEEL ARCH TRIMS AND REAR RH DOOR	New	4,000.00	2,250.00
Gross Labour Cost (\$\$)			6,672.00	3,832.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >