



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1007/2021/JT
DATE : 13-Dec-21
WIP : 58377

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Guo Qiang

5 days exclude 1 Sunday

Johnny Boo

15-Feb-22

OWNER'S NAME : MR YEO YIAN CHONG
ADDRESS : 31 JURONG WEST STREET 41
#16-20
SINGAPORE 649412
TELEPHONE : HP +65 90993113
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210105665
VEHICLE NO : **SJP 9198 B**
MODEL CODE : AUDI Q5 SB ADVANCE
MODEL YEAR : 31/8/2021
ENGINE NO : DGK 006934
CHASSIS NO : WAUZZZF7M2101820
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Dec-21
PLACE OF ACCIDENT : TANJONG PAGAR / KEPPEL ROAD
JUNCTION AFTER YELLOW BOX

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJP 9198 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00 \$	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00 \$	750.00
3	TO RESPRAY REAR BUMPER, RHS REAR BUMPER COVER, RHS REAR FENDER, BOTH REAR WHEEL ARCH TRIMS AND REAR RH DOOR.	\$	4,000.00 \$	2,250.00
4	TO RENEW RHS REAR RIM AND TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00 \$	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 \$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,672.00 \$	3,832.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJP 9198 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
1	REAR BUMPER	1	\$	2,405.00	
2	REAR BUMPER SPOILER	1	\$	913.00	
3	REAR BUMPER LOWER COVER - RH	1	\$	261.00	
4	REAR BUMPER CLOSING ELEMENT - RH	1	\$	300.00	
5	REAR BUMPER TOWING EYE COVER - RH	1	\$	121.00	
6	REAR BUMPER TRIM INNER / OUTER - RH	2	\$	458.00	\$ 366.40
7	REAR PARKING AID SENSOR SUPPORT OUTER - RH	1	\$	95.00	
8	TAIL LIGHT - RH	1	\$	699.00	
9	REAR BUMPER GUIDE SECTION - RH	1	\$	106.00	
10	REAR WHEEL ARCH COVER - LH / RH	2	\$	1,166.00	\$ 932.80
11	ALUMINIUM RIM	1	\$	1,314.00	\$ 1,051.20
12	REAR WHEEL HOUSING LINER - RH	1	\$	278.00	
13	RHS REAR TYRE	S/N		TBC	
14	SUNDRIES		\$	400.00	
TOTAL SPARE PARTS		:	\$	8,516.00	\$ 2,350.40
TOTAL LABOUR CHARGES		:	\$	6,672.00	\$ 3,832.00
GRAND TOTAL		:	\$	15,188.00	\$ 6,182.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-12/02/22



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT