



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21012786/Aqf3n2	Date: 17/01/2022
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SFC 2688R	Veh. Inspected	SKD 6906X
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10012956/KY	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	17/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HARRIER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTEKB3GH70J003404	Colour	WHITE
	Odometer	60842 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	16/12/2021	Inspection Date	20/12/2021
	Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	