

TP Budget Direct.
Xiao Chun

SKD6906X 2018 Oct.

Toyota Harrier 1998cc

JTEKB36H70J003404

Front Bumper	Debond	811.20.	✓
Front Bumper clips.	in	30(SN)	✓
Front Bumper Side Holder LH.	2nd	99.10.	✓
Front Bumper Side Garnish LH.	NP in	75.40.	X
Front Bumper lower Garnish.	NP in	340.20	X.
Front Bumper Reinforcement.	} NP in	521.70	X
Front Bumper Sponge.		172.40	X
Headlamp HH.	cut	3303.10	✓
Headlamp lower Bracket	in	127.40	X.
Headlamp lower Sponge.	cut	112.20.	✓
Front LH wheel Rim.	NP in	1569.	X.

4325.60 S.N. 30
3244.20.

SKD6906X

Panel Beating.

Spray Painting.

Wiring.

To perform wheel alignment.

730

~~600~~ 300

~~600~~ 400

~~50~~ 30

150 X

total: 4004.20

h/s: 32K. ✓

03 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: