

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012788/AQY3N2**Date:** 04/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00011002101
<b>Claimant Vehicle No :</b>	SMY7855T	<b>Insured Vehicle No :</b>	SKU2415H
Date of Loss:	14/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207346/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMY7855T</b>	Engine No:	PE21595991
Make & Model:	MAZDA CX-30, 2.0 (A)	Chassis No:	JM6DM2W7AM0103610
Reg. Date:	25/03/2021 (Man. Year: 2021)	Odometer:	16649 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/55R18	Rear Tyre Size:	215/55R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,527.70	1,791.84	2,735.86	60.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	730.00	120.00	14.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,377.70</b>	<b>2,521.84</b>	<b>2,855.86</b>	<b>53.11</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>5,377.70</b>	<b>2,000.00</b>	<b>3,377.70</b>	<b>62.81</b>

**INSPECTION**

Date of Assignment:	24/01/2022	
Date Inspected:	10/01/2022	Inspected At: Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	2.0 days	

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2022)
<b>Parts:</b>	M1-SUV	MAZDA CX-30 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMY7855T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,020.00 F	*1,020.00 FL
2	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	64.60 F	*- FL
3	1		*FRONT BUMPER TOP COVER	Deformed	389.40 F	*389.40 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	542.20 F	*- FL
5	1		*FRONT GRILLE	Cracked	560.30 F	*560.30 FL
6	1		*FRONT GRILLE CHROME MOULDING	Cracked	298.20 F	*149.10 FL
7	1		*FRONT GRILLE LOGO	Necessary	58.50 F	*58.50 FL
8	1		*HEADLAMP LH	Not Necessary	1,464.50 F	*- FL
9	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
10	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
11	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
12	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,527.70</b>	<b>2,227.30</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	435.46
<b>Total Parts (\$)</b>	<b>4,527.70</b>	<b>1,791.84</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING	New	400.00	400.00
3	WIRING	New	50.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>850.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >