

(08/11/13) wef

ASS. REC. BY: *marcus*REF: *CCG/A1621012794/Uea3***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lump Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: *M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /*

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: *Good / Fair / Poor / Burnt*Steering: *In order / Jammed / Leaked / Burnt or*Brake: *In order / Jammed / Leaked / Burnt or*

Modi: Nil / S/Rim / STD A/Rim-or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

16/12/21

D.O.I.

2/3/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/4/22 12/25/40 informed Angs.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI
☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3116J
SYED SALMAN ABBAS
BLK 34 BAYSHORE ROAD
21-01
SINGAPORE 469976
TEL : FAX :
PH : 92201194
ATTN :

ESTIMATE BILL

Number : EB00005837
Date : 17/12/2021
Case No : AD00012249
Vehicle No : SMF7261G
Chassis : JTDZS3EU60J034338
Year of Mfr : 2018
Policy No :
Model : TOYOTA PRIUS PLUS (AUTO)

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	REAR BUMPER	1.0	556.40	0	556.40
2	REAR BUMPER REFLECTOR RH	1.0	59.80	0	59.80
List Price - Parts Sub Total					616.20
3	REVERSE SENSOR	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					280.00
Parts Total					896.20
4	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	350.00	0	350.00
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	300.00
6	ANTI-RUST COATING	1.0	50.00	0	50.00
7	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					850.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : ONE THOUSAND EIGHT HUNDRED SIXTY-EIGHT AND CENTS FORTY-THREE ONLY			Less Excess		0.00
			SUBTOTAL		1,746.20
			GST 7.00%		122.23
			TOTAL		1,868.43

Date of accident : 16/12/2021 12:45 PM. Place : SYED ALVI ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE