

ASS. REC. BY:

REF:

C72/ 210 7296/ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMZ 77207

Yr Regn:

05, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prior

c.c

1798

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

66300

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B31FU 903 092920

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Sailun

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

15/12/21

D.O.I.

16/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/12 8 4409.28 Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

Not Authored
Recovery B4 paint

B4409.28

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ7720T

LAD2112-008

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 DEC 2021

SMZ7720T

JTDKB3FU903092920

TOYOTA

PRIUS GEN 4

15/12/2021

China-

18/05/2021

PART

LIST

1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	Bz 1,300.70	✓
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	R 603.20	X
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	P 38.60	X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	P 193.50	X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	P 390.60	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	P 926.00	X
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	P 321.10	X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R 110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R 97.50	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	R 238.30	X
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	R 43.50	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	R 13.30	✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	R 26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	Bz 1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	P 193.50	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	P 97.40	X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	P 293.00	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	P 926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	P 206.70	X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	R 34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	R 15.40	✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	R 21.90	✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	R 87.10	X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	R 98.90	X
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	P 1,436.60	X

Trans-cab Auto Services Pte Ltd**LAD2112-008**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ7720T

1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>R</i>	871.50	<i>X</i>
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>P₂</i>	139.80	<i>X</i>
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>R₂</i>	594.80	<i>✓</i>
1	FENDER SUB-ASSY, FRONT RH	\$	<i>R</i>	977.80	<i>X</i>
1	COVER, REAR BUMPER	\$	<i>R</i>	485.60	<i>X</i>
TOTAL		\$		12,079.00	
25%		\$		3,019.75	
		\$		9,059.25	

Special Nett

1	REAR FENDER LINER CLIP	\$	<i>na</i>	65.00	<i>X</i>
1	FRT FENDER LINER CLIP	\$	<i>na</i>	65.00	<i>X</i>
1	REAR BUMPER RETAINER CLIP	\$	<i>na</i>	75.00	<i>X</i>
2	DOOR TRIM CLIP	\$	<i>na</i>	150.00	<i>X</i>
2	DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	160.00	<i>X</i>
TOTAL		\$		515.00	
TOTAL PARTS		\$		9,574.25	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>600</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>600</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>na</i> 380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>1100</i>

Trans-cab Auto Services Pte Ltd**LAD2112-008**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ7720T

To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>601</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
TOTAL	\$	5,100.00	
Over All Total	\$	14,674.25	

(PART-BY-PART) Repair Days**20 Days***5 days***LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: