

Not Authorized
Recovery B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ7720T

LAD2112-008

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 DEC 2021

SMZ7720T

JTDKB3FU903092920

TOYOTA

PRIUS GEN 4

15/12/2021

Clinic-

18/05/2021

PART

LIST

1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	1,300.70	✓
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	603.20	X
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	38.60	X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	193.50	X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	390.60	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	926.00	X
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	321.10	X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	97.50	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	238.30	X
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	43.50	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	13.30	✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	193.50	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	97.40	X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	293.00	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	206.70	X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	15.40	✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	21.90	✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	98.90	X
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	1,436.60	X

Trans-cab Auto Services Pte Ltd**LAD2112-008**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ7720T

1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>n</i>	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>ln</i>	139.80	X
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>R</i>	594.80	✓
1	FENDER SUB-ASSY, FRONT RH	\$	<i>n</i>	977.80	X
1	COVER, REAR BUMPER	\$	<i>n</i>	485.60	X

TOTAL	\$	12,079.00
25%	\$	3,019.75
	\$	9,059.25

Special Nett

1	REAR FENDER LINER CLIP	\$	<i>na</i>	65.00	X
1	FRT FENDER LINER CLIP	\$	<i>na</i>	65.00	X
1	REAR BUMPER RETAINER CLIP	\$	<i>na</i>	75.00	X
2	DOOR TRIM CLIP	\$	<i>na</i>	150.00	X
2	DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	160.00	X

TOTAL	\$	515.00
--------------	-----------	---------------

TOTAL PARTS	\$	9,574.25
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ 240.00 *600*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 *600*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 1,600.00 *600*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair. \$ *na* 380.00 X

Putty And Spray Painting Of The Affected Portion. \$ 1,600.00 *1100*

Trans-cab Auto Services Pte Ltd**LAD2112-008**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ7720T

To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>601</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
TOTAL	\$	5,100.00	
Over All Total	\$	14,674.25	

(PART-BY-PART) Repair Days**20 Days***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**