



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300353

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 17/01/2023  
Reference CC3/CTI21012797/Vpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHA 9173A  
Insured Veh. GBE 7362J  
Claim No. SNM21D207332C02  
Policy No. DMCVSNW00142072100  
Accident Date 15/12/2021  
Inspection Date 16/12/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                          |      |                             |            |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|------|-----------------------------|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                          |      | Ref: CC3/CTI21012797/Vpa3q2 |            |
|                                                                                                                                        |                                                                          |      | Date: 17/01/2023            |            |
|                                                                                                                                        |                                                                          |      | Code: CTI                   |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                          |      |                             |            |
| Insured Veh.                                                                                                                           | GBE 7362J                                                                |      | Veh. Inspected              | SHA 9173A  |
| Policy No.                                                                                                                             | DMCVSNW00142072100                                                       |      | Coverage (\$)               | 0.00       |
| Claim No.                                                                                                                              | SNM21D207332C02                                                          |      | Excess (\$)                 | 0.00       |
| Assign From                                                                                                                            |                                                                          |      | Assign Date                 | 16/12/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                          |      |                             |            |
| Make & Model                                                                                                                           | HYUNDAI IONIQ                                                            |      | c.c                         | 1580       |
| Engine No.                                                                                                                             | HIDDEN                                                                   |      | Year of Reg.                | 2019       |
| Chassis No.                                                                                                                            | KMHC851CVLU180575                                                        |      | Colour                      | YELLOW     |
| Odometer                                                                                                                               | 134756 KM                                                                |      | Steering                    | IN ORDER   |
| Brakes                                                                                                                                 | IN ORDER                                                                 |      | Modification                | SPORTS RIM |
| General                                                                                                                                | GOOD                                                                     |      |                             |            |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                          |      |                             |            |
|                                                                                                                                        |                                                                          | Size | Make                        | Balance    |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                               |      | WEST LAKE                   | 5 mm       |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                               |      | WEST LAKE                   | 5 mm       |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                               |      | WEST LAKE                   | 5 mm       |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                               |      | WEST LAKE                   | 5 mm       |
| <b>4. Description of Damages</b>                                                                                                       |                                                                          |      |                             |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br><br>DAMAGES SEE DETAILS.                                                         |                                                                          |      |                             |            |
| <b>5. General Information</b>                                                                                                          |                                                                          |      |                             |            |
| Accident Date                                                                                                                          | 15/12/2021                                                               |      | Inspection Date             | 16/12/2021 |
| Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |      |                             |            |
| <b>5a. Remarks</b>                                                                                                                     |                                                                          |      |                             |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |      |                             |            |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                          |      |                             |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                          |      | <b>3 Working Days</b>       |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9173A

| Qty                                | Description of Parts                        | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------|-------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                             |             |                           |                   |
| 1                                  | COVER -RR BUMPER                            | CUT         | 459.40                    | 459.40            |
| 1                                  | MOULDING ASSY -RR BUMPER C                  | SCRATCHED   | 451.25                    | 451.25            |
| 1                                  | BEAM -RR BUMPER                             | DENTED      | 493.50                    | 493.50            |
| 10                                 | BUMPER COVER CLIP REAR                      | NECESSARY   | 22.00                     | 22.00             |
| 1                                  | LAMP ASSY -REAR FOG                         | CRACKED     | 201.50                    | 201.50            |
| 10                                 | ANTENNA ASSY -SMARTKEY                      | SERVICEABLE | 405.00                    | -                 |
| 1                                  | PANEL ASSY -TAIL GATE                       | DENTED      | 2,480.40                  | 2,480.40          |
| 1                                  | EMBLEM -IONIQ                               | NECESSARY   | 31.30                     | 31.30             |
| 1                                  | EMBLEM -HYBRID                              | NECESSARY   | 24.30                     | 24.30             |
| 1                                  | SYMBOL MARK -H                              | NECESSARY   | 28.00                     | 28.00             |
| 1                                  | REAR BUMPER STAY LH (ADDITIONAL)            | DENTED      | 138.10                    | 138.10            |
| 1                                  | REAR BUMPER STAY RH (ADDITIONAL)            | DENTED      | 138.10                    | 138.10            |
| 1                                  | REAR BUMPER UNDER COVER LH (ADDITIONAL)     | CUT         | 108.00                    | 108.00            |
| 1                                  | REAR BUMPER LOWER MOLDING (ADDITIONAL)      | CUT         | 155.00                    | 155.00            |
| 1                                  | REAR BUMPER CENTRE UNDER COVER (ADDITIONAL) | CUT         | 225.00                    | 225.00            |
|                                    | LESS 20% DISCOUNT                           |             | -1,072.17                 | -991.17           |
|                                    |                                             |             | 4,288.68                  | 3,964.68          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                             |             |                           |                   |
| 1                                  | PROTECTOR MAT (SN)                          | NECESSARY   | 50.00                     | 50.00             |
| 1                                  | VEHICLE NUMBER PLATE REAR (SN)              | CRACKED     | 50.00                     | 50.00             |
| 2                                  | WINDSCREEN AHESIVE -310MLC (SN)             | NECESSARY   | 46.00                     | 46.00             |
| 1                                  | BOOTLID LOGO CCTPL MOQ30 (SN)               | NECESSARY   | 30.00                     | 30.00             |
| 1                                  | REAR BOOTLID TEL NUMBER CCTP (SN)           | NECESSARY   | 30.00                     | 30.00             |
| 1                                  | APP LOGO REAR BONNET CCPL (SN)              | NECESSARY   | 40.00                     | 40.00             |
|                                    |                                             |             | 246.00                    | 246.00            |
| <b><u>LABOUR</u></b>               |                                             |             |                           |                   |
|                                    | PANEL BEATING.                              |             | 800.00                    | 700.00            |
|                                    | SPRAYPAINT CHARGE.                          |             | 600.00                    | 500.00            |
|                                    | CHECK ALL LIGHTING.                         |             | 50.00                     | 20.00             |
|                                    | REMOVE/REFIX REVERSE SENSOR .               |             | 50.00                     | 20.00             |

Report Ref No. CC3/CTI21012797/Vpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                         | Description of Parts               | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|------------------------------------|-----------|---------------------------|-------------------|
|                             | REMOVE/REFIX REAR W/SCREEN GLASS . |           | 120.00                    | 120.00            |
|                             |                                    |           | 1,620.00                  | 1,360.00          |
| GRAND TOTAL                 |                                    |           | 6,154.68                  | 5,570.68          |
| RECOMMENDED COST OF REPAIRS |                                    |           |                           | 5,570.68          |

Report Ref No. CC3/CTI21012797/Vpa3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHA 9173A

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 9173A

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHA 9173A**

**RE-INSPECTION**

