

Not Notified
Heavy B&P
4-5 days

Date: 16.12.2021
Vehicle No: SMW8522H
Model: MITSUBISHI OUTLANDER 2.0 ELEGANCE
Chassis: GF7W-0601251
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLA8808L
Date of Accident: 16.12.2021
Estimator: Victor
Surveyor: Kenneth

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	TAILGATE	1	Bu	\$1,350.00	✓
2	TAILGATE INNER TRIM BOARD	1	bu	\$350.00	X
3	REAR TAILGATE "OUTLANDER" EMBLEM	1	nu	\$95.00	✓
4	REAR TAILGATE "MIVEC" EMBLEM	1	nu	\$75.00	✓
5	REAR TAILGATE LOCK	1	R	\$220.00	X
6	REAR WEATHERSTRIP	1		\$300.00	?
7	REAR WINDSCREEN MOULDING	1	nu	\$150.00	✓
8	REAR BUMPER	1	Bu / cnt	\$1,160.00	✓
9	REAR BUMPER SIDE BRACKET RH	1		\$100.00	?
10	REAR BUMPER REFLECTOR RH	1	bu	\$145.00	X
11	REAR LOWER BUMPER	1	Ref / cnt	\$820.00	✓
12	REAR DIFFUSER	1	CM	\$1,600.00	✓
13	END PANEL	1		\$365.00	?
14	END PANEL TOP COVER	1	bu	\$165.00	X
SUB TOTAL				\$6,895.00	
LESS 10%				-\$689.50	
PARTS TOTAL				\$6,205.50	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	TAILGATE INNER TRIM CLIPS	1		nu \$120.00	X
2	REAR WINDSCREEN SEALANT	1		nu \$100.00	40sn
3	END PANEL JOINT SEALANT	1		\$80.00	?
4	REVERSE SENSOR	1		\$280.00	?
5	REVERSE CAMERA	1		bu \$200.00	X
6	REAR BUMPER CLIPS	1		nu \$100.00	50sn
7	REAR BUMPER CLIPS	1		Agreat \$100.00	X
8	END PANEL TOP COVER CLIPS	1		nu \$50.00	X
S/N TOTAL				\$1,030.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR REAR ACCIDENT AREA. \$1,200.00 ?

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA. \$1,000.00 600p

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 16.12.2021
Vehicle No: SMW8522H
Model: MITSUBISHI OUTLANDER 2.0 ELEGANCE
Chassis: GF7W-0601251
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLA8808L
Date of Accident: 16.12.2021
Estimator: Victor
Surveyor: Kenneth

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$150.00	120%
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM.	\$120.00	60%
LABOUR CHARGES TO REMOVE & REPLACE REVERSE SENSOR.	\$100.00	50%
TO CONDUCT DIAGNOSTIC, RESET FAULT CODE & MEMORY.	\$150.00	?
TO CHECK WIRING & CENTRAL LOCKING SYSTEM.	\$100.00	20%
TO TUFF COAT AND UNDERSEAL MATERIAL.	\$100.00	?

LABOUR TOTAL	\$2,920.00
--------------	------------

TOTAL	\$10,155.50
-------	-------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind, Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

