

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

**India International Insurance Pte Ltd**

64 , Cecil Street # 04 - 05

IOB Building

Singapore 049711

Tel : 6347 - 6100

Fax : 6224 - 4174

**Quotation**

DATE : 17.12.2021

VEH NO : SLA3020A

MODEL : Mazda 3

D O A : 15.12.2021

YR REF : GBJ8817G

*Asher.*

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SLA3020A (MAZDA 3)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Rear Bumper <i>Distorted</i>	1	1,047.30 ✓
2	Rear Bumper Reflector - RH <i>new</i>	1	54.90 ✗
3	Rear Bumper Reinforcement <i>new</i>	1	537.30 ✗
4	Rear End Panel <i>Rys</i>	1	530.40 ✗
			<i>1047.30</i>
			<i>837.84</i>
			\$ 2,169.90
			(433.98)
			\$ 1,735.92
	<b>S/NET ITEMS</b>		
1	Rear Bumper Clips <i>new</i>	1	30.00 ✓
2	Reverse Sensor <i>new</i>	1	280.00 ✗
3	Rear End Panel Sealant <i>new</i>	1	60.00 ✗
			<i>30</i>
			370.00
	<b>Total parts</b>		\$ 2,105.92

**LABOUR CHARGE**

1	To knocking & pull out rear portion & renew above parts	600.00 ✓ <i>400</i>
2	To putty & spray up paint works	800.00 ✓ <i>500</i>
3	To check wiring	50.00 ✓ <i>30</i>
4	To remove reverse sensor	100.00 ✓ <i>50.</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SLA3020A (MAZDA 3)

5 To spray tuff coat

1040

150.00 ~~60.~~

1,700.00

Grand Total

\$ 3,805.92

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 1907.84

L/s: 1.5K.

03Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: