

SIN SHENG AUTO WORKSHOP PTE LTD

REGISTRATION NO.: 202019500G

NO. 5 TUAS AVE 3 SINGAPORE 639405

TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Wah & Hua Pte Ltd

11 Kranji Crescent

WH Building

Singapore 728656

Attn: Motor Claims Department

Estimate No : ES2021/0045

Date : 21/12/2021

Vehicle No : XE1328M

Make/Model : IVECO / TRAKKER

Date of Accident : 04/12/2021

Prepared By : Hoe

S/N	Description	Qty	Unit Amount (\$\$)	Amount (\$\$)
<u>Parts (List)</u>				
1	Bumper, LH <i>bt/</i>	1	1,178.08	1,178.08
2	Bumper bracket <i>bt/</i>	1	65.04	65.04
3	Bumper center <i>bt/</i>	1	2,105.79	2,105.79
4	Headlamp, LH <i>cr/</i>	1	2,115.50	2,115.50
5	Bumper signal lamp <i>cr/</i>	1	106.65	106.65
6	Bumper sport lamp <i>cr/</i>	1	141.94	141.94
7	Headlamp cover <i>ms/</i>	1	27.81	27.81
8	Corner panel, LH <i>cr/</i>	1	2,220.05	2,220.05
9	Upper fender <i>cr/</i>	1	1,399.85	1,399.85
10	Fender garnish <i>scr/</i>	1	104.94	104.94
11	Fender protector <i>scr/</i>	1	185.50	185.50
12	Fender extension <i>xnn</i>	1	397.46	397.46 X
13	Fender lower <i>cr/</i>	1	1,017.18	1,017.18
14	Fender lower garnish <i>xnn</i>	1	141.04	141.04 X
15	Fender bracket <i>xnn</i>	1	576.96	576.96 X
16	Lower step <i>cr/</i>	1	604.45	604.45
17	Lower step garnish <i>xnn</i>	1	71.77	71.77 X
18	Mirror assy, LH <i>cr/</i>	1	1,493.30	1,493.30
19	Door glass, LH <i>repair</i>	1	495.50	495.50 XR
20	'Trakker 410 ES' logo <i>cr/</i>	1	169.50	169.50
				14,618.31
Less: 10%				(1,461.83)
Price after dics				13,156.48
<u>Nett</u>				
1	Sealant <i>xnn</i>			40.00 X
2	Black and yellow sticker <i>cr/</i>			30.00
Parts total				13,226.48

12,935.58

10%

11,642.02

30

SIN SHENG AUTO WORKSHOP PTE LTD

REGISTRATION NO.: 202019500G

NO. 5 TUAS AVE 3 SINGAPORE 639405

TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Labour charges

- To remove and replace door glass
- To panel beat/repair LHS body
- To dismantle/replace above-mentioned parts
- To spray painting on affected areas

Labour total

950.00

750

1,000.00

700

1,950.00

1450

Loss of Use : 6 days @ S\$250/day

TOTAL

15,176.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair

Hp 90010068

6 days

45

21/12/21 @ 1100

Resy after repair

11642.02

301.00

14501.00

13,122.02

20%

10,497.61

L/S - \$10,500