

ASS. REC. BY: TGuin

REF:

CS/MSG21012801/Bqf3

Shuan Chan

## ASSIGNMENT

From: \_\_\_\_\_ Date: 20/12/2021

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLL 8627J

at Workshop m/s Bifrost Auto

of 8 Kaki Bt Aves Premier # 01-49

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. 267078

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 100,000/-

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLL 8627J Yr Regn: 13/3/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: BMW 34 2.0 c.c 1995

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 72301 T/Radio: Insured / Std / NI / NA

Eng/No: B1000 194N20B 20A

C/No: WBALL52090E750933

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRM / STD A/Rim or

Tyre Size: F: 235/35/19

R: 265/30/19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 16/12/2021 D.O.I. 20/12/2021

Survey held at Bifrost Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 11,000/- - 12,000/-

11/02/22@4.05pm revised &amp; email Chhia Nyuk Pui to seek mandate at LS \$11200, 10 days.

Recommended COR is LS \$11,150.00 TGuin

28/03/22@4.54pm Email Chhia Yuk Pui re-seek mandate at LS \$11250.

30/03/22@4.11pm Nyuk Pui informed that Please confirm the fender price and confirm if we can finalise repair cost with workshop at \$8750.

MV 100,000/-

PV 68,550/- TGuin

NV 31,441/- 28/12/2021

06/06/22@9.40am confirmed with Andrew LS \$8750, 10 days. (Red \$24538.11, 74%)

Date/Time, File Pass to? \_\_\_\_\_ : Prelim. Report

1) 06/06 Typist \_\_\_\_\_ : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

3) \_\_\_\_\_

4) \_\_\_\_\_

Rep. Formist: MER-TP

Lump Sum/IC: 8750

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: \_\_\_\_\_ : Site Insp (\$ 1)

\_\_\_\_\_ : Interview (\$ )

\_\_\_\_\_ : Tech. Invs (\$ )

\_\_\_\_\_ : Weekend (\$ )

\_\_\_\_\_ : Others

TOTAL

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Shiau Chan

Estimate

Vehicle No:

Make and model:

Chassis :

SLL8627J

BMW Z4

WBALLS2090E750933

2017  
List priceQty Spare parts

1	Bootlid	S		✓ 2,186.00 DDV
1	Bootlid centre emblem	S	54.95	69.50 NECV
1	Bootlid outer handle with switch	S		✓ 156.70 } SSCV
1	Bootlid outer handle with switch inner bracket	S		34.20 } NDX
1	Bootlid lock	S	295.00	711.46 JMV
1	Bootlid weatherstrip	S		156.80 ? NDX
1	Bootlid third brake lamp	S		233.10 NDX
1	Bootlid third brake lamp gasket	S		23.22 NNX
1	Bootlid RH hinge	S	115.00	183.40 } BTV
1	Bootlid RH hinge absorber	S		159.30 } NDX
1	Bootlid LH hinge	S	115.00	183.40 } BTV
1	Bootlid LH hinge absorber	S		159.30 NDX
1	Bootlid RH rubber stopper	S		23.10 } NNX
1	Bootlid LH rubber stopper	S		23.10 } NNX
1	Bootlid inner trim	S		503.60 } NDX
1set	Bootlid inner trim clips	S		80.00 } NNX
1	Bootlid retactable canopy motor	S		3,120.20 } NDX
1	Bootlid retactable canopy motor hinge	S		831.00 } NDX
1	Rear bumper	S		✓ 1,279.00 BRV
1set	Rear bumper clips	S	30.00	80.00 NECV
1	Rear bumper lower garnish	S		382.20 ? NDX
1	Rear bumper RH reflector	S		78.30 } ? NDX
1	Rear bumper LH reflector	S		78.30 } ? NDX
1	Rear bumper RH side PDC reverse sensor	S		284.50 NDX
1	Rear bumper RH centre PDC reverse sensor	S	245.00	284.50 } SCV
1	Rear bumper LH centre PDC reverse sensor	S	245.00	284.50 } NDX
1	Rear bumper LH side PDC reverse sensor	S		284.50 NDX
4	Rear bumper PDC reverse sensor holders	S		✓ 149.40 NECV
4	Rear bumper PDC reverse sensor seal	S		✓ 13.00 NECV
1	Rear bumper reinforcement	S		✓ 606.12 } BTV
1	Rear bumper reinforcement inner garnish	S		67.90 } NDX
1	Rear bumper RH side bracket	S		65.60 } ? NDX
1	Rear bumper LH side bracket	S		65.60 } ? NDX
1	Rear bumper centre bracket	S		✓ 156.80 } BTV
1	RH taillamp	S	565.00	583.00 BRV
1	RH taillamp sponge gasket	S	20.00	33.40 NECV
1	RH taillamp panel	S		166.00 ? NDX



1	LH taillamp	\$	565.00	583.00	CUTV
1	LH taillamp sponge gasket	\$	20.00	33.40	NECV
1	LH taillamp panel	\$		166.00	NDX
1	End panel	\$	695.00	782.30	DDV
1	End panel inner garnish	\$		95.40	BRV
1	End panel inner garnish clips	\$	30.00	50.00	?NECV
1	End panel RH side garnish	\$		112.00	} NDX
1	End panel RH side garnish cover	\$		55.60	
1	End panel LH side garnish	\$		112.00	
1	End panel LH side garnish cover	\$		55.60	} NDX
1	Rear compartment panel top board	\$		316.00	
1	Rear compartment panel top board RH side garnish	\$		93.20	} NDX
1	Rear compartment panel top board LH side garnish	\$		93.20	
1	Rear RH fender	\$		1,632.10	DDV
1	Rear RH fender inner trim	\$		334.20	?NDX
1	Rear RH fender inner trim clips	\$	30.00	80.00	NECV
1	Rear LH fender	\$		1,632.10	DDV
1	Rear LH fender inner trim	\$		334.20	} NDX
1	Rear LH fender inner trim clips	\$		80.00	
1	RH exhaust silencer	\$		1,714.02	} NDX
2	RH exhaust silencer chrome finishers	\$		231.40	
1	RH exhaust silencer clamp	\$		67.15	
1	RH exhaust silencer gasket	\$		34.18	
1	LH exhaust silencer	\$		1,714.02	
2	LH exhaust silencer chrome finishers	\$		231.40	
1	LH exhaust silencer clamp	\$		67.15	
1	LH exhaust silencer gasket	\$		34.18	

10931.57 \$ ~~10,931.57~~ 24,513.80  
-5% \$ 539.83 1,225.69  
10384.99 \$ ~~11,256.74~~ 23,288.11

#### Qty Spare parts

- 1 Rear number plate
- 1 Rear number plate holder
- 1 End panel joint sealant
- 1 Rear RH fender joint sealant
- 1 Rear LH fender joint sealant
- 1 RH taillamp panel joint sealant
- 1 LH taillamp panel joint sealant
- 1 Bootlid spoiler (after market items)

#### Special Nett price

\$	30.00	70.00	BT ✓
\$		50.00	NS X
\$	30.00	80.00	NECV
\$	30.00	80.00	NECV
\$	30.00	80.00	NECV
\$		40.00	} NN X
\$		40.00	
\$	1000.00	2,400.00	BRV ✓
	1120.00		

#### Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.  
To panel beating, cut / weld and re-align all affected panels

\$ 1400.00 2,400.00 ✓

Spray painting on affected panels	\$ 1,000.00	1,600.00 ✓
Check wiring and lighting system	\$	100.00 NNX
Apply rust coating chemical on affected panels	\$	180.00 NNX
Remove and replace bootlid inner mechanism to new bootlid	\$ 80.00	150.00 ✓
Remove and replace rear inner trims, garnish and boards to assist repair	\$	400.00 NNX
Remove and replace rear bumper reverse sensors and wire harness to assist repair	\$ 60.00	150.00 ✓
Remove and replace exhaust silencers, chrome finishers and heat shields to assist repair	\$	480.00 NNX
Remove and reinstall fuel tank, pipes, hoses and sensors to assist repair	\$	220.00 NNX
Remove and reinstall canopy assy to assist repair. Re-adjust to the original position	\$	750.00 NNX
Remove and reinstall seats, seats garnish, carpet and seat belts to assist repair	\$	380.00 NNX
Reset and diagnose control unit and fault code after repair	\$	350.00 NNX
		<u>2,540.00</u>
	\$	33,288.11

Survey  
20/12/2021  
Tevin Lim  
1335 hrs

Resurvey  
22/12/2012  
1245 hrs  
Tevin Lim

Lump sum repair  
Repair days 10

Parts	<del>10,256.74</del>	10384.99
SN	1,120.00	
Labour	2,540.00	
	<del>13,916.74</del>	14044.99
@ 20%	2783.35	
	<del>1,123.35</del>	11200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS ~~11,150.00~~

Tevin Lim

29/12/2021



Shuan Chan  
24

Date of Accident : 16/12/2021 Accident Time: 1930 (24-HR-FORMAT)  
Accident Place : Selatar West Road turning to TPE/SLC  
Vehicle Reg. No (Car plate No.) : SLL 8627J Vehicle Make/Model: BMW 24  
Insurance Company : AXA Policy No. GAS84492/1  
Name of Registered Owner : Company / Individual Mohammed Razali Bin Arifin  
ID of Registered Owner : Co Reg No: \_\_\_\_\_ Owner's NRIC No: 57800098H  
: Co Contact No: \_\_\_\_\_ Owner's Contact No: 83184069  
DRIVER'S Name : \_\_\_\_\_ DRIVER'S NRIC No: \_\_\_\_\_  
DRIVER'S Date of Birth : 11/1/1978 DRIVER'S License Pass Date 12/10/2018  
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Self  
DRIVER'S Address : Blk 350 Anchorvale Road #17-19  
DRIVER'S Contact No./ Alt No. : 1) \_\_\_\_\_ 2) \_\_\_\_\_  
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)  
Email Address : Mohd. Razali.godless@gmail.com  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim \ Other Party \ Claim Own Insurance  
Number of Passengers (including Driver): 1 Name & Gender: \_\_\_\_\_  
Was the accident reported to the police? YES \ NO  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any injuries, if yes (name of the injured person) Driver

Other Party Driver's Particulars (if any)

Vehicle Reg No: <u>WCL430R</u>	Vehicle Reg No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan







**SINGAPORE  
POLICE FORCE**



T/20211217/7026

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20211217/7026

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/12/2021 13:33		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: MOHAMMED RAZALI BIN ARIFIN			Address: 350 ANCHORVALE ROAD #17-129 SINGAPORE 540350		
ID Type / ID No.: NRIC NO / S7800098H			Contact No.: Home/Office: Mobile: 83184069		
Nationality: SINGAPORE CITIZEN			Email: MOHD.RAZALIGODBLESSSS@GMAIL.COM		
Sex: Male	Age: 43	Date of Birth: 01/01/1978	Type of Informant: Driver		
Race: Malay		Language: English		Institution / School Name:	
Occupation: Environmental engineer		Driving Licence Information: Class: Date of Expiry:			

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/12/2021 19:30	Type of Location: Bend
Location:  SELETAR WEST LINK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
SLL8627J	Car	BMW	Z4+2.0+A	White		0
WC2430R	Lorry					0



**SINGAPORE  
POLICE FORCE**



T/20211217/7026

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20211217/7026

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLL8627J	AXA INSURANCE SINGAPORE PTE LTD	GA584492	22/09/2021	21/09/2022

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOHAMMED RAZALI BIN ARIFIN	ID No.	S7800098H
Related Vehicle	SLL8627J (Car)	Contact No.	83184069
Hospital/Clinic	24 HOUR WALK-IN CLINIC	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	16/12/2021	Date	NIL
No. of Days granted Medical Leave	07	Degree of	Slight

Brief Details.

I was traveling along seletar west link turning left to CTE/SLE. There is 2 lanes when turning. Approaching the turn, the lorry was on my right side after I completed the left bend, the lorry switched to my lane and hit the rear portion of my vehicle. I have video camera to proof my statement.





**SINGAPORE  
POLICE FORCE**



T/20211217/7026

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20211217/7026

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPB /  
TAY CHUN KEEN

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by Singpass. No signature is  
required.

Date/Time:  
17/12/2021 13:33

Classification Of Case:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	098H
Vehicle Details	
Vehicle No.:	SLL8627J
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2021
Vehicle Make:	B.M.W.
Vehicle Model:	Z4 2.0 A
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	B1000194N20B20A
Chassis No.:	WBALL52090E750933
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$44,965.00
Original Registration Date:	13 Mar 2017
First Registration Date:	13 Mar 2017
Transfer Count:	2
Actual ARF Paid:	\$54,951.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Mar 2027
PARF Rebate Amount:	\$41,213.00
Intended COE Rebate Details	
COE Expiry Date:	12 Mar 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$52,600.00
COE Rebate Amount:	\$27,346.00
Total Rebate Amount:	\$68,559.00

The information contained herein is correct as at 28 Dec 2021

OK

MV 100,000/2

PV 68,559/2

NV 31,441/2

Tan Min  
28/12/2021