

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 11 Feb 2022

Preliminary Advice

Insured : WC2430R
Vehicle No
TP Vehicle : SLL8627J
No
Make : BMW Z4
Date of : 20/12/2021
Inspection
Accident Date : 16/12/2021
Assignment Date : 17/12/2021
Est. Duration of : 10
Repair
Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)
8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT
SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,288.11
Revised Amount	:S\$	14,044.99
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,044.99

Lump Sum Repair	:S\$	11,200.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

() The vehicle is economical for repair

() The vehicle is not economical for repair

() Part-by-Part repair

(X) Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.