



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/Mr Wang Jun Yong Erwin</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMK4991B / 12/04/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAD6811VK6279473</td></tr> <tr> <td>Engine No</td><td>G3LCKP008081</td></tr> <tr> <td>Make/Model</td><td>KIA/STONIC 1.0 A SX BJ3 W SUNROOF</td></tr> <tr> <td>Colour/Trim</td><td>UD CLEAR WHITE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Mr Wang Jun Yong Erwin	Reg No/Reg Date	SMK4991B / 12/04/201	Date In/Mileage	/ 0	Chassis No	KNAD6811VK6279473	Engine No	G3LCKP008081	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF	Colour/Trim	UD CLEAR WHITE / WK SATURN BLACK
Cust No/Name	/Mr Wang Jun Yong Erwin														
Reg No/Reg Date	SMK4991B / 12/04/201														
Date In/Mileage	/ 0														
Chassis No	KNAD6811VK6279473														
Engine No	G3LCKP008081														
Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF														
Colour/Trim	UD CLEAR WHITE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/12/2021/ 17:52	BLE	261 / Edwin Caina	44120
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
E PNT88000 RENEW BONNET & FR BUMPER REPAIR RHF FENDER	1.5 X 410			600	1600.00
E PNT98000 RESPRAY BONNET, FR BUMPER & RHF FENDER	2 X 350			700	1050.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00
M SUNDRY SUPPLY FR NUMBER PLATE WITH CASING CUT					50.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS					40.00
M SUNDRY SUPPLY BODY PNL SEALANT				40	60.00
M SUNDRY Sundries					20.00
M LAMP ASSY-HEAD,RH	1.00	1845.00	20.00		1476.00
M PANEL ASSY-HOOD	1.00	904.00	20.00		723.20
M HINGE ASSY-HOOD,LH	1.00	43.00	20.00		34.40
M HINGE ASSY-HOOD,RH	1.00	43.00	20.00		34.40
M LATCH ASSY-HOOD	1.00	101.00	20.00		80.80
M CLIP-HOOD INSULATING PAD MTG	13.00	1.00	20.00		10.40
M COVER-FR BUMPER UPR	1.00	476.00	20.00		380.80
M CAP-FRONT HOOK	1.00	5.00	20.00		4.00
M GRILLE-FRONT BUMPER	1.00	96.00	20.00		76.80
M COVER-FR BUMPER,LWR	1.00	367.00	20.00		293.60
M SKID PLATE-FR BUMPER	1.00	55.00	20.00		44.00
M LIP ASSY-FRONT BUMPER	1.00	32.00	20.00		25.60
M BRACKET-FR BUMPER SIDE,RH	1.00	13.00	20.00		10.40
M MOULDING-FRONT BUMPER A/INTAKE	1.00	61.00	20.00		48.80
M ABSORBER-FRONT BUMPER ENERGY	1.00	98.00	20.00		78.40
M COVER-FR BUMPER FOG LAMP,RH	1.00	64.00	20.00		51.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Mr Wang Jun Yong Erwin
	Reg No/Reg Date	SMK4991B / 12/04/201
	Date In/Mileage	/ 0
	Chassis No	KNAD6811VK6279473
	Engine No	G3LCKP008081
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	UD CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/12/2021/ 17:52	BLE	261 / Edwin Caina	44120
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M GRILLE ASSY-RADIATOR	✓ BK	1.00	324.00	20.00	259.20
M BEAM COMPLETE-FR BUMPER	✓ + nn	1.00	544.00	20.00	435.20
M ORNAMENT-KIA NO.115	✓ ncc	1.00	32.00	20.00	25.60

Estimate

SURVEYOR NAME : Steve (LKK) 20/12/21, 5:00pmSURVEYOR SIGNATURE : OP-M ALDATE : Excels - ?REMARKS : PIP
My Bn sy
4 djs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

	Nett	7,062.80
7% GST on	7062.80	494.40
Total Payable		7,557.20

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.