

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1015/2021/JT
DATE : 15-Dec-21
WIP : 58774

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIEW SHUE CHING CAROL
ADDRESS : 808 THOMSON ROAD
#16-18
SINGAPORE 298190
TELEPHONE : HP +65 97527885
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100498703-04
VEHICLE NO : **SLK 6084 T**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 20/1/2017
ENGINE NO : CVN 024435
CHASSIS NO : WAUZZZF49HA067453
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Dec-21
PLACE OF ACCIDENT : JUNCTION OF SOUTH BRIDGE ROAD
AND UPPER CROSS ST



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLK 6084 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00 280	✓
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00 ✓	✓
4	TO REMOVE AND REINSTALL REAR SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPET, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE RHS SEAT BELT AND HEAD AIRBAG.	S/N \$ 1,800.00 x	
5	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW RHS REAR DOOR. TO CUT OUT AND WELD RHS SILL PANEL. TO REPAIR RHS REAR FENDER AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 1000 ✓	✓
SUB TOTAL LABOUR CHARGES		: \$ 7,690.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLK 6084 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY REAR BUMPER, DOOR HANDLE, RHS REAR DOOR, RHS FRONT DOOR, RHS REAR FENDER, RHS SILL PANEL AND DOOR ENTRANCE.	\$ 5,000.00	2750 ✓
7	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓ ✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 13,162.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: MORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 6084 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR SIDE PANEL TRIM - RH <i>Rejis</i>	1	\$ 3,034.00	✓	
2	REAR DOOR <i>Dented</i>	1	\$ 3,192.00	✓	2553.60
3	REAR OUTER DOOR SEAL - RH <i>Re</i>	1	\$ 205.00	✓	164
4	BONDING AGENT	1	NN 49.00	?	
5	CLEANING SOLUTION	1	NN 68.00	?	
6	APPLICATOR	1	NN 8.00	?	
7	REAR DOOR SEALING STRIP <i>me n</i>	1	\$ 17.00	✓	
8	REAR DOOR ATTACHEMENT PARTS <i>me n</i>	1	\$ 860.00	✓	
9	REAR DOOR CATCH - RH	1	NN 120.00	?	
10	REAR WHEEL HOUSING LINER - RH <i>me n</i>	1	\$ 240.00	+	
11	REAR WHEEL HOUSING LINER ATTACHEMENT PARTS <i>me n</i>	1	TBC	✓	
12	ALUMINIUM RIM <i>at</i>	1	\$ 983.00	✓	786.4
13	ARYLIC SEALANT <i>me n</i>	S/N	\$ 180.00	+	
14	CAVITY WAX	S/N	\$ 140.00	+	
15	STONE CHIP <i>Re</i>	S/N	\$ 180.00	✓	180
16	METAL FILLER POWDER <i>me n</i>	S/N	\$ 280.00	+	
17	SUNDRIES		\$ NEC 400.00	?	8.72
TOTAL SPARE PARTS		:	\$ 9,956.00		
TOTAL LABOUR CHARGES		:	\$ 13,162.00		
GRAND TOTAL		:	\$ 23,118.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
 SURVEYED DATE : *17/12/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT