

Our Job Ref No : 305498028

Date : 18/12/21

**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyal Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD7109J

15/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SMR7204J

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_


(c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$2,200.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature:  \_\_\_\_\_

Signature:  \_\_\_\_\_

Name : CHIANG

Name : Thevan

Tel : 62148314

Date : 20/12/21

Fax : 65468156

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

COMFORT GRO ENGINEERING PTE LTD.

REPAIR ESTIMATE\*

15.12.2021

VEHICLE NO SHD7109J  
 MAKE REG. 10.11.2016  
 MODEL HYU- 140

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
			\$35.60	\$35.60
1	REAR BUMPER BRACKET SIDE RH		\$2.20	\$22.00
10	REAR BUMPER CLIPS			\$553.00
1	REAR BUMPER			\$228.00
1	REAR BUMPER UNDER COVER			\$428.40
1	REAR BUMPER REINFORCEMENT			\$565.60
1	BOOTLAMP RH			\$52.40
1	BOOTLID CDRI			\$67.90
1	BOOTLID I-40 EMBLEM			\$697.80
1	TAIL LAMP RH			\$2,171.40
1	REAR FENDER LH			\$85.00
1	BOOTLID CHROME MOULDING		\$32.00	\$32.00
1	REAR BUMPER REFLECTOR RH			\$4,939.10
				\$987.82
				\$3,951.28
				\$50.00
1	REAR BUMPER ADVERTISEMENT			\$100.00
1	REAR FENDER RH ADVERTISEMENT			\$50.00
1	REAR BUMPER MAT			\$135.70
1	REVERSE SENSOR			\$322.13
	<b>Labour Charge</b>			\$600.00
	Panel Beating			\$800.00
	Spray Painting Charge			\$50.00
	Check lighting and wiring			\$60.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
	<b>TOTAL LABOUR</b>			\$1,570.00
	<b>ESTIMATE TOTAL</b>			\$5,843.41

n/c  
n/c  
DT  
scr  
X SUC  
scr  
n/c  
n/c  
scr  
X  
n/c  
CUA  
n/c  
n/c  
n/c  
cut  
280  
250  
20  
20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan@lkhauto.com  
 82235769  
 16/12/21 1600  
 CS before paint + photo  
 2 days up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: