

Our Job Ref No : 305498221
Date : 28/12/21

ENGINEERING

Cambridge Engineering Ltd
50 Leighton Drive Singapore 339955
Fax 334 8122

FINALIZATION FORM

To : LKK

Attn: THEVAN

Vehicle Reg No SH7101D

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:

Z The repair job shall bill to NTUC GBE63T

2. The finalized amount shall be

(a) Spare Parts after List discount

(b) Labour Charges _____

Total for Part-By-Part Repair Cost _____

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost	\$7,000.00
---------------------------	------------

3. Estimated normal period for repairs **3** working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5 Thank you for your assistance

We confirm the estimates and finalized amount

Signature : _____

Name : CHIANG

Tel: 62148314

Fax : 65468156

Signature: _____

Name : Tha'an

Date : 3/1/2/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

Vehicle No.: SH7101D
Make : TOYOTA
Model : PRIUS G4
DOA : 15.12.2021

LKK Auto Consultants hence notify

Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Insurance"
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed
- Is subject to final approval from Insurance Company

Date : REG 14.03.2019

Insurance: NTUC

MVA : CHIANG

Admin:

Part No.	Parts Description	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70
1	REAR TRUNK LID LOGO (PRIUS)			\$60.80
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90
1	REAR TRUNK COVER			\$1,126.60
1	REAR WINDSCREEN GLASS W/MOULDING			\$1,778.30
1	REAR TRUNK LID GLASS W/MOULDING			\$1,569.70
1	ROOF TOP CENTRE GARNISH			\$456.30
2	ROOF TOP GARNISH LH /RH		\$136.80	\$273.60
1	SPOILER ASSY			\$953.70
1	REAR BUMPER			\$458.60
1	REAR BUMPER UNDER COVER			\$552.60
1	REAR BUMPER REINFORCEMENT			\$318.80
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40
2	REAR BUMPER UNDER SIDE LH/RH		\$232.00	\$464.00
1	REAR BUMPER UNDER COVER CENTRE			\$252.00
1	REAR BUMPER TOWING COVER			\$82.70
1	REAR END PANEL			\$602.10
1	REAR END PANEL GARNISH			\$165.80
2	TAIL LAMP UPPER LH/RH		\$557.90	\$1,115.80
2	TAIL LAMP LOWER LH/RH		\$548.40	\$1,096.80
10	REAR BUMPER CLIPS			\$22.00
	SUB TOTAL			\$12,570.60
	LESS 25%			\$3,142.65
	DISCOUNTED TOTAL			\$9,427.95
1	REAR TRUNK LID APPS STICKER			\$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER		\$30.00	\$60.00
1	REAR FENDER PETROL STICKER			\$20.00
1	REAR BUMPER MAT			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$135.70
				\$280.13
	Labour Charge			
	Panel Beating			\$840.00
	Spray Painting Charge			\$800.00
	Wiring Charge			\$60.00
	Remove/Refix windscreen and lower glass			\$200.00
	Tuff Kote			\$90.00
	Remove/Refix Reverse Sensor			\$60.00

Therun @ LK Auto

82235769

16/12/21 1700

L/S after repair photo

3 days w/p