			_	- · · · · · · · · · · · · · · · · · · ·	
Our Job Ref No :	305498026			IGINEERING	
Date :	20/12/21		6010	ortDelGro Engineering Pte Ltd byang Drive Singapore 508969	
FINALIZATION FORM			Fax: (6546 8156	
To :	LKK		Fax:		
Attn : Mr	Thevan				
Vehicle Reg No. : SHAT	726T CTPL			15/12/2021	
The survey and estimates of	the repairs of the above-men	tioned vehicle	are as follows	:-	
The repair job shall bil		ITUC	***	GBF 569X	
2. The finalized amount s				\$977.04	
(a) Spare Parts aft				\$1,220.00	
(b) Labour Charges				\$2,197.04	
lotal for Part-I	By-Part Repair Cost			The state and another country and the state of the state	
(c.) Lumpsum Repa Total for Lumps Final Lumpsu r	um repair cost after Less:	20%			
 Estimated normal period for repairs: 3 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 					
working days 5. Thank you for your ass Signature:	sistance.	fina	e confirm the ealized amount		
Name : Ms. Loke	YY	-	me :	Thevan.	
Tel : 6214835	,	− Da	te :	21/17/2/	
Fax : 6546815		- -			
For Official Use Only					
Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day		YES			
2. Loss of Income Paid		NO			
3. Survey Fees					
LTA Search Fee Medical Fees (on behalf of driver, if applicable)	\$7.49 / \$2.00				
6 Overrun					
Remarks: Towing fee incu	rred				

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA7726T

Make

: HYUNDAI

Model : IONIQ(G3) Date: 16/12/2021

Insurance: NTUC

MVA: MS. LOKE YY

		111171	
Qty Parts Description / Labour	Туре	Unit Price	Amount
1 FRT BUMPER COVER			\$430.90
10 FRT BUMPER CLIPS			\$22.09
1 FRT BUMPER SIDE BRACKER RH			\$28.00
1 HEADLAMP RH			£1 002 65
1 FRT FENDER SHIELD RH			\$1,993.63 \$164.70
1 FRT FENDER RH			\$588.80
1 EMBLEM BLUE – DRIVE RH			\$26.60 \$346.40
1 FRT WHEEL HUB CAP RH			\$346.40
1 FRT BUMPER SIDE MOULDING RH			\$186,90
SUB TOTAL			\$3,787.95
LESS 20%			\$757.59
DISCOUNTED TOTAL			\$3,030.36
FRT TYRE RH		5	√,° X,\$216.00
FRT FENDER ADVERTISEMENT LOGO RH			1ec/\$100.00
			\$316.00
Labour Charge			
PANEL BEATING			\$1,050.00
SPRAY PAINTING CHARGE			\$600.00
FRT WHEEL ALIGNMENT			\$120.00
CHECK ALL LIGHTING			\$60.00
TOTAL LABOUR			\$1,830.00
ESTIMATE TOTAL			\$5,176.36
ESTIMATE TOTAL			φυ, 170.30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran@LHHauto. (:om

\$2235769

16/12/21 1630

PIP bfr paint photo
3 clays up/

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: