| <u>ASS</u>  | IGNMEN'I  |
|---|---|
| From Cale   | Veli No: 5447728T VIROGN: 30/9 /20                                  |
| Estimated Cost:   | Type: M.Car / M.Cycle / Bus / Van / Lorry / (ax) Primo Mover /      |
| OD/TP/WS/JP RES/ OD RES/ EVA / INV / MV                         | Truck / Trailer or  |
| To Inspect Vehicle No:  | Moro: Hyundai lonig co 1580   |
| of Workshop m/s   | Colour Dlue NC: . Insured/SId/HI/HA                                 |
| 61  | Sp.Reading 23/580 T/Radio: Insured / Std / NI / NA                  |
| Insured:  | Eng/No:   |
| Policy No.  | CNO: KMHC85/CULU189943  |
| Clalms No. MT/1154866-002                                       | Gen. Cond: (80) / Folr / Poor / Burnt                               |
| Sum Insured: Excess:  | Steering: Interior / Jammod / Leaked / Burnt or                     |
| (Client's Record)   | Brake: Investor / Janimed / Leaked / Burnt or                       |
| Make of Vch:  | Modi: NII / (IRIm) / STD A/RIm or .                                 |
|   | Tyro Size: F: 195/65/R13  |
| (Delies Confilm)  | R: 195/65/15  |
| (Policy Condition)  Remark: The veh had commenced Its  N/S  O/S | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /     |
| repair at the time of inspection.                               | TOYOTYOKO or WESTIA he  |
| Bal or Market Value:  | Fron Roor   |
| Constitution Volume   | R/Bal, 5 mm R/Bal, 5 mm   |
| IDAG Academ Apoli.  | L/Bal. 5 mm L/Bal. 5 mm   |
| GIA 7 TH SCEN.  | D.O.A. 15/12/21 D.O.I. 16/12/21 1630                                |
|   | Survey held at CDGE   |
|   | Des. of Damages : Frt Rear   O/S   N/S   U/C   Rooflop or           |
| CA ! REV ! REP. ! 24 HRS  |   |
| Dale,Person Contacted:  | The U/C / Chassis frame / Body Structure affected due to collision. |
| Date / Time Action / Instruction                                | ,   |
| No gia givia  | g \$2107.04, 2 doys (Pod \$2070.22 <del>500)</del>                  |
| 21/12/21 Thevan finalised with Ms Loke final fi                 | g \$2197.04, 3 days. (Red \$ <del>2979.32, 58%)</del>               |
|   |   |
|   |   |
|   |   |
|   |   |
| ;   |   |
| Oxed Time. File Pass 67 Proll. Roport ; Day                     | rs Of Ropalr: 3   |
| Ros   | survey No. of Trip: 1 Survey Fee:                                   |
| 1/23/12 Typist : Final Roport                                   | Transportation:   |
| Add Fee:  | Site Insp (\$)_s-FSSi   |
| <del></del>   | : Interview (\$ ) Flinis  |
| Fewert Folias: TP   | Trech, this (\$ ) (like)  |
| TP. 2197.04   | : West and the  |
| 2107.04   | 16431   |

NS/INC21012811/Vgc

## COMFORT TRANSPORTATION PTE LTD

PP

REPAIR ESTIMATE

Vehicle No. : SHA7726T/

Make Model : HYUNDAI

Date: 16/12/2021

Insurance: NTUC

MVA: MS. LOKE YY

| del | : IONIQ(G3)                                 | MVA: MS. LOKE YY |            |                     |
|-----|---|------------------|------------|---------------------|
| Qty | Parts Description / Labour                  | Type             | Unit Price | Amount              |
| -77 | 1 FRT BUMPER COVER                          |                  |            | \$430.90            |
|     | 10 FRT BUMPER CLIPS                         |                  |            | \$22.09             |
|     | 1 FRT BUMPER SIDE BRACKER RH                |                  |            | \$28.00             |
|     | 1 HEADLAMP RH                               |                  |            | \$1,993.65          |
|     | 1 FRT FENDER SHIELD RH                      |                  |            | \$164.70            |
|     |   |                  |            | \$588.89            |
|     | 1 FRT FENDER RH<br>1 EMBLEM BLUE – DRIVE RH |                  |            | enc co              |
|     | 1 FRT WHEEL HUB CAP RH                      |                  |            | \$26.60<br>\$346.40 |
|     | 1 FRT BUMPER SIDE MOULDING RH               |                  |            | \$186.90            |
|     | 1 FRT BOMPER SIDE MODEDING KIT              |                  |            |                     |
|     | SUB TOTAL                                   |                  |            | \$3,787.95          |
|     | LESS 20%                                    |                  |            | \$757.59            |
|     | DISCOUNTED TOTAL                            |                  |            | \$3,030.36          |
|     |   |                  |            | vc X                |
|     | FRT TYRE RH                                 |                  | 3          | \$216.00            |
|     | FRT FENDER ADVERTISEMENT LOGO RH            |                  | Ý          | 1ec/\$100.00        |
|     | THE TENDERADVERNIOLINE IN 2000 I MA         |                  | ĺ          | \$316.00            |
|     |   |                  |            |                     |
|     | Labour Charge                               |                  |            |                     |
|     | PANEL BEATING                               |                  |            | \$1,050.00          |
|     | SPRAY PAINTING CHARGE                       |                  |            | \$600.00            |
|     | FRT WHEEL ALIGNMENT                         | -                |            | \$120.00            |
|     | CHECK ALL LIGHTING                          |                  |            | \$60.00             |
|     | TOTAL LABOUR                                |                  |            | \$1,830.00          |
|     |   |                  |            |                     |
|     | ESTIMATE TOTAL                              |                  |            | \$5,176.36          |
|     |   |                  |            |                     |
|     |   |                  |            |                     |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran@Lthauto.lom

\$7235769

16/12/21 1630

PIP bfr paint photo
3clays up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Oale:



## ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Maintine + 03 Sales Gray Workshops 206 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575777

Date/Time: 16.12.2021 08:53

Page : 1

Team:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4152607

JC NO305498026

MILEAGE

**FUEL** 

**JSTOMER** 

R/MS

EL. (R)

(P)

COMFORT TRANSPORTATION PTE LTD

7010045

JSTOMER NO. TOBESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

NODEL IONIQ(G3) YR OF MANU. 30.09.2020

REGN NO. SHA7726T

HYUNDAI

15.12.2021 16:35

Date

E.....F

CHASSIS CODE KMHC851CVLU189943

TARGET DATE COMPLETION DATE/TIME:

ISCOUNT CARD NO.

ne of Service Advisor

be returned to Service Reception upon collection

JOB DESCRIPTION


Accident Date: 15.12.2021

NATURE: 3P 15.12.2021

S/NO

LABOR CODE

DESCRIPTION



| HECKED &                 | PASSED OUT BY: |      |                       |                      |
|--------------------------|----------------|------|-----------------------|----------------------|
|                          | SERVICE ADVIS  | SOR  | -                     | CUSTOMER'S SIGNATURE |
| nowledgem                | nent Slip      |      | Exit Pass             |                      |
| ne:<br>No.:<br>icle No.: | SHA7726T       | YY . | Vehicle No.: SHA7726T |                      |
|                          |                |      |                       |                      |

Name of Service Advisor

To be kept by Security Guard

Signature/Date