

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012820/GVY3N2**Date:** 02/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00092012101	
<b>Claimant Vehicle No :</b>	SNB7628S	<b>Insured Vehicle No :</b>	GBK5290P	
Date of Loss:	10/12/2021	Nature of Claim:	TP	Claim No: SNM21D207189/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNB7628S</b>		Engine No:	2AR2625612
Make & Model:	TOYOTA ALPHARD, 2.4 (A)		Chassis No:	AGH300369835
Reg. Date:	13/09/2021 (Man. Year: 2021)		Odometer:	27318 km
Colour:	Black			
Engine Capacity:	2493 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,143.30	5,064.95	4,078.35	44.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,640.00	630.00	27.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,413.30</b>	<b>6,704.95</b>	<b>4,708.35</b>	<b>41.25</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,350.00</b>		
<b>(\$\$)</b>	11,413.30	5,350.00	6,063.30	53.12
<b>+ GST 7.00/7.00% (\$\$)</b>	798.93	374.50	424.43	53.12
<b>Nett Amount (\$\$)</b>	<b>12,212.23</b>	<b>5,724.50</b>	<b>6,487.73</b>	<b>53.12</b>

**INSPECTION**

Date of Assignment:	06/04/2022	
Date Inspected:	20/12/2021	Inspected At: Vin's Auto Pte Ltd (Vin's Auto) Sin Ming AutoCity,, 160 Sin Ming Drive #03-03 Singapore 575722
Estimated Period of Repair:	6.0 days	

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jun 2022)
<b>Parts:</b>	M1-MPV	TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNB7628S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Buckled	2,856.80 FL	*1,661.10 FL
2	1		*REAR RH DOOR OUTER MOULDING	Not Necessary	121.13 FL	*- FL
3	1		*REAR RH DOOR LOWER PROTECTOR	Cut	752.40 FL	*752.40 FL
4	1		*REAR RH DOOR POWER WINDOW MOTOR	Not Necessary	711.60 FL	*- FL
5	1		*REAR RH DOOR POWER WINDOW GEAR	Not Necessary	321.70 FL	*- FL
6	1		*REAR RH FENDER	Buckled	1,521.10 FL	*1,521.10 FL
7	1		*REAR RH FENDER LOWER PROTECTOR	Cut	421.10 FL	*159.60 FL
8	1		*REAR RH WHEEL KNUCKLE ARM	Bent	657.40 FL	*657.40 FL
9	1		*REAR RH WHEEL KNUCKLE ARM BEARING	Bent	911.84 FL	*405.00 FL
10	1		*REAR RH WHEEL TRAILING ARM	Not Necessary	511.60 FL	*- FL
11	1		*REAR RH WHEEL LOWER ARM (BIG)	Bent	530.00 FL	*530.00 FL
12	1		*REAR RH WHEEL LOWER ARM (SMALL)	Not Necessary	380.00 FL	*- FL
13	1		*REAR RH WHEEL SPORT RIM	Cut	1,870.80 FS	*800.00 FS
					<b>Sub Total (\$\$)</b>	<b>11,567.47      6,486.60</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,424.17      1,421.65</b>
					<b>Total Parts (\$\$)</b>	<b>9,143.30      5,064.95</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WHEEL ALIGNMENT	New	150.00	60.00
2	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	280.00	180.00
3	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	New	280.00	120.00
4	TO REPAIR DAMAGES	New	780.00	680.00
5	TO SPRAY PAINTING	New	780.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>2,270.00</b>	<b>1,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >