

Vin's

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Vehicle Details

Make & Model : Toyota ALPHARD 7-SEATER 2.5
SC CVT

Chassis No : AGH300369835

Registration No : SNB7628S

Vin's Motor Pte Ltd

160 Sin Ming Drive

#03-03 Sin Ming Autocity

Singapore 571722

Tel : 6459 1795

Fax : 6459 1795

Registration No. 199906057G

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Claim Details

Case Ref. No.

Date

Accident Date

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

11-12-2021

Signature:

Date:

Third Party Vehicle Details

Registration No : GBK5290P

S/N	Description	Qty	Amount (\$S)
1	REAR RH DOOR / <i>Buc</i>	1.00	\$2,856.80
2	REAR RH DOOR OUTER MOULDING <i>X NN</i>	1.00	\$121.13
3	REAR RH DOOR LOWER PROTECTOR <i>Cut</i>	1.00	\$752.40
4	REAR RH DOOR POWER WINDOW MOTOR <i>X NN</i>	1.00	\$711.60
5	REAR RH DOOR POWER WINDOW GEAR <i>X</i>	1.00	\$321.70
6	REAR RH FENDER / <i>Buc</i>	1.00	\$1,521.10
7	REAR RH FENDER LOWER PROTECTOR <i>Cut</i>	1.00	\$421.10
8	REAR RH WHEEL KNUCKLE ARM ?	1.00	\$657.40
9	REAR RH WHEEL KNUCKLE ARM BEARING <i>BT</i>	1.00	\$911.84
10	REAR RH WHEEL TRAILING ARM <i>X NN</i>	1.00	\$511.60
11	REAR RH WHEEL LOWER ARM (BIG) ?	1.00	\$530.00
12	REAR RH WHEEL LOWER ARM (SMALL) <i>X NN</i>	1.00	\$380.00
13	REAR RH WHEEL SPORT RIM / <i>Cut</i>	1.00	\$2,494.40

\$12,191.07

Discount: -25%

(\$3,047.77)

\$9,143.30

14	TO CHECK WHEEL ALIGNMENT	1.00	\$150.00 <i>60</i>
15	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$280.00 <i>180</i>
16	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	1.00	\$280.00 <i>120</i>
17	TO REPAIR DAMAGES	1.00	\$780.00 <i>680</i>
18	TO SPRAY PAINTING	1.00	\$780.00 <i>600</i>

Subtotal w/o GST:

\$11,413.30

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

6 Days.

4/5

After repair photos.

29/12/21.

Gua Ruy.

R017896
11.12.21 16:01
SNB7628S
160-0303



SNB7628S

Factory Japan 2019.0.2 : Toyota : Alphard / Vellfire : H30 Series : AGH30W
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°15'	-0°15'	-1°00' 0°30'
6°14'	6°14'	5°10' 6°40'
0°02'	0°02'	-0°02' 0°08'
11°41'	11°41'	10°50' 12°20'
11°26'	11°26'	9°50' 12°50'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°30'	-0°30'	-1°00' 0°30'
6°28'	6°28'	5°10' 6°40'
0°13'	0°13'	-0°02' 0°08'
11°35'	11°35'	10°50' 12°20'
11°05'	11°05'	9°50' 12°50'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°15'	0°14'	-0°45' 0°45'
-0°13'	-0°13'	-0°45' 0°45'
0°05'	0°06'	
0°15'	0°14'	-0°05' 0°15'

Rear : Left

Actual	Before	Specified Range
-1°17'	-1°17'	-1°30' 0°00'
0°08'	0°08'	0°03' 0°12'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°40'	-2°41'	-1°30' 0°00'
-0°14'	-0°14'	0°03' 0°12'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
1°24'	1°24'	-0°45' 0°45'
-0°05'	-0°06'	0°05' 0°25'
0°11'	0°11'	
0mm	0mm	