



AIG- OD CLAIM
SURVEY: 20/12/21
LKK- STEVE

VEHICLE NO : SMY 4741 H

MODEL : CIT/GRAND C4

WIP : 17266

Material	:	\$	<u>8,010.40</u>
Labour	:	\$	<u>4,095.00</u>
Sub-Total	:	\$	<u>12,105.40</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>11,805.40</u>
GST 7%	:	\$	<u>826.38</u>
Grand Total	:	\$	<u>12,631.78</u>
Finalise By/Date : <u>LARRY ON 15/02/22</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk.end)

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /CHOY KIN MAN Reg No/Reg Date SMY4741H / 10/03/2021 Date In/Mileage 05/01/2022/ 14982 Chassis/Package VF73AHNS4LJ595358 /CS3PT Engine No 10TMA30041489 Make/Model CIT/GRAND C4 SPACETOUREX EXCLUSIVE Colour/Trim MOF ARTIC STEEL / IXF YATAGO GREY



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
FAX00001	Credit	14/02/2022/ 17:28	BLE	884 / Lauro Songcuan	17266	0	
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1250.00 ✓
RENEW FRONT BUMPER, BONNET & RH FRONT FENDER, REPAIR LH FRONT FENDER							
E PNT98000							1520.00 ✓
SPRAY PAINT FRONT BUMPER, BONNET, LH FRONT FENDER & RH FRONT FENDER							
A 25000001							500.00 ✓
VACUUM & TOP UP AIRCON GAS							
A 54900099							50.00 ✓
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							225.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
E PNT88000							50.00 ✓
REMOVE & REFIT FRONT PARKING ASSIST SENSOR							
M SUNDRY							40.00 ✓
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							40.00 ✓
SUPPLY BODY PANEL SEALANT							
M SUNDRY							20.00 ✓
SUNDRIES							
S SPECIALISTJOB							50.00 ✓
SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)							
E PNT88000							100.00 ?
REMOVE & REFIT AIRCON CONDENSER AND RADIATOR							
X EXC							-300.00
EXCESS							
E PNT88000							250.00 X
REPAIR FRONT SUPPORT PANEL → Supp							
X FRONT BUMPER ✓				1.00	1074.00	20.00	859.20 ✓
X BUMPER BRACKET ?				1.00	330.00	20.00	264.00 ?
X BUMPER MOULDING ✓				1.00	207.00	20.00	165.60 ✓
X BUMPER MOULDING ✓				1.00	227.00	20.00	181.60 ✓
X BMPR RUBBR BOOT ✓				1.00	363.00	20.00	290.40 ✓
X GUARD GRILLE INFERIEUR ✓				1.00	311.00	20.00	248.80 ✓
X BADGE SUPPORT ✓				1.00	205.00	20.00	164.00 ✓

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /CHOY KIN MAN Reg No/Reg Date SMY4741H / 10/03/2021 Date In/Mileage 05/01/2022/ 14982 Chassis/Package VF73AHNS4LJ595358 /CS3PT Engine No 10TMA30041489 Make/Model CIT/GRAND C4 SPACETOUREX EXCLUSIVE Colour/Trim MOF ARTIC STEEL / IXF YATAGO GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	14/02/2022/ 17:28	BLE	884 / Lauro Songcuan	17266	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X CHEVRON EMBLEM SUPERIEUR ✓	1.00	161.00	20.00	128.80 ✓
X CHEVRON EMBLEM INFERIEUR ✓	1.00	161.00	20.00	128.80 ✓
X BRACKET SET ✓	1.00	125.00	20.00	100.00 ✓
X BRACKET SET LAT ✓	1.00	125.00	20.00	100.00 ✓
X BUMPER BRACKET ✓	1.00	516.00	20.00	412.80 ✓
X REAR DUCT RH ?	1.00	119.00	20.00	95.20 ?
X FACE CROSSMEMBR SUP ?	1.00	226.00	20.00	180.80 ?
X AIR BULKHEAD RH ?	1.00	108.00	20.00	86.40 ?
X AIR BULKHEAD ?	1.00	154.00	20.00	123.20 ?
X FRONT WING RH ASS ✓	1.00	571.00	20.00	456.80 ✓
X ENGINE BONNET ASS ✓	1.00	1042.00	20.00	833.60 ✓
X SOUND PROOFING ✓	1.00	235.00	20.00	188.00 ✓
X CONDENSER ✓	1.00	1175.00	20.00	940.00 ✓
X FRONT LIGHT RH ✓	1.00	409.00	20.00	327.20 ✓
X HEADLIGHT ASSY RH ✓	1.00	718.00	20.00	574.40 ✓
X BUMPER MOULDING	1.00	328.00	20.00	262.40 X
X LOW FR PAN FIX	1.00	158.00	20.00	126.40 X
X BUMPER BRACKET	1.00	194.00	20.00	155.20 X
X COOLING LIQUID DRUM 2L PAE -35	2.00	25.00	20.00	40.00 X
X HEAT SHIELD	1.00	58.00	20.00	46.40 X
X RADIATOR NEW ?	1.00	663.00	20.00	530.40 ?
Z TEXT				
AIG - OD CLAIM				
SURVEY: STEVE (LKK) 20/12/2021				
DOA: 18/12/2021				
05 DAYS				

Supp.


642.00

* change price

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	8,010.40			
Labour	3,945.00			
Standard Menu	0.00	7% GST on	Nett	11,805.40
Specialist Job	50.00			826.38
Diagnostics Job	0.00		Total Payable	12,631.78
Sundry/Others	-200.00		Paid	0.00
Total(w/o GST)	11,805.40		Total Due	12,631.78

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMY 4741 H**

		<u>Cost (\$)</u>
<u>Materials</u>		
1	Bumper Moulding	328.00 — BR
2	Low FR Pan Fix	158.00 — BR
3	Bumper Bracket	194.00 — BR
4	Cooling Liquid Drum 2L PAE-35 (2 pcs)	50.00 — hec
5	Heat Shield	58.00 — DD
		788.00
20% Discount		157.60
		630.40
<u>Labour</u>		
1	Repair Front Support Panel	250.00 —
		880.40
7% Gst		61.63
Total		
		942.03

Thank You.

Yours faithfully

CYCLE & CARRIAGE FRANCE PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE

TEL: 6568 4658

FAX : 6567 5258

CAR NO: SMY4741HWIP: 17266

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	② BUMPER BRACKET CR /	? / SUPP			96 760 518 80
2	⑤ FRONT BUMPER TRIM CR /	? / SUPP			16 175 375 80
3	③S BUMPER FIXING STIFFENER CR /	? / SUPP			16 175 370 XY
4	③A AIR VENTILATOR DUCT RIGHT CR /	? / SUPP			98 142 079 80
5	② FRONT PANEL CROSSMEMBER CR /	? / SUPP			98 144 713 80
6	⑥ COOL AIR AFT-RECYCL PARTITION RIGHT	? / SUPP			96 770 152 80
7	③ COOL AIR AFT-RECYCL PARTITION CR /	? / SUPP			96 760 385 XY
8	⑥ ENGINE RADIATOR BT	? / SUPP			98 114 011 80
9	HRT BUMPER FASTENING 5 PCS /	? / SUPP			16 131 807 80
10	COOLANT (+2)	? / SUPP			
11	Turbocharger heat shield	? / SUPP		23/12/21	98 177 923 80
12		? / SUPP			
13		? / SUPP			
14	REPAIR HRT SUPPORT PNL \$ 250	? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: C4SURVEYOR: STEVE



Reg no: SMY 4741 H
Before to use DIAGBOX
to check all the fault

Battery state check procedure before customer delivery (MyDSP note): Click here!

Home Documentation Measurements Reports

PROGRESS OF THE AUTOMATIC DETECTION OF THE VEHICLE

- ✓ VIN : VF73AHNS4LJ595358
- ✓ Vehicle data retrieved
- ✓ Identification of the vehicle complete

CITROEN C4 PICASSO / C4 SPACETOURER (B78) ESTATE - LEISURE 1.2
Pure Tech 130 (EB2ADTS EURO 6.3) STT TYPE 8-SPEED AUTOMATIC
GEARBOX



Automatic detection of the vehicle complete

Script automatic vehicle detection : 12_00





Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

12



Built-in systems interface

BSI2010_EV (12 Faults)

B181A 87

Fault in the response from the electric steering lock to the request for locking/unlocking

Properties

Cause

Local

Status

Intermittent

Features

No reply

B1808 87

Fault in the unlocking of the immobiliser by the engine management ECU

Properties

Cause

Local

Status

Intermittent

Features

Request missing

B1166 15

Front right direction indicator control fault

Properties

Cause

Local

Status

Intermittent

Features

Open circuit or short circuit to positive

B1167 15

Front left direction indicator control fault

Properties



Key No: 8444741 H
Order to use JTAG
to force all the same
Job Done by G.C Test.

Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT



Built-in systems interface

BSI2010_EV



Engine management ECU

CMM_VD56



Urea ECU

Communication error

Anti-lock Braking System (ABS)
or Electronic Stability Program
(ESP)

ESP90

Automatic or piloted manual
gearbox

BVA_AXN8

Controls under the steering
wheel

★ ECU not recognised

Down-grade mode: this information is
not guaranteedControls on the steering wheel /
integral controls steering wheel

VCI

Left-hand windscreen wiper
motor

MOTEV_UDS

Right-hand windscreen wiper
motor

MOTED_UDS



Air conditioning

BCC



Instrument panel

CIROCCO














Rain and brightness sensor

PLUIE_LUMINOSITE_UDS



Airbags and pretensioners ECU

RBG_UDS

	Trailer relay unit	Not present
	External CD player	Not present
	Audio amplifier	Not present
	Multifunction video camera (CMF)	Not present
	Anti-theft alarm	Not present
	Intrusion alarm siren	Not present
	Vehicle Distance Assistance	Not present
	Seat driver position memory module.	Not present
	Right-hand reversible seat belt inertia reel	Not present
	Left-hand reversible seat belt inertia reel	Not present
	Dynamic headlamp height adjuster	Not present
	Supplies protection and management unit	Not present
	Automatic gearbox electric control ECU	Not present
	Hands-free unit	Not present
	Service module / Independent telematic unit	Not present
	Voltage maintaining device	Not present
	Motorised Boot Unit	Not present