

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719
E-mail: xinyaauto@singnet.com.sg
Tel: 6270 3481 Fax: 6278 7522

Date : 15-Dec-21

Address : HALDEN UNITED INVESTMENT PTE LTD
BLK 350C CANBERRA ROAD
#08-223
SINGAPORE 753350

Reference : TP 1299/12/21
Vehicle No : GBJ7339B
Make/Model : PEUGEOT PARTNER
Insurance Co. : AXA

RE : QUOTATION REPAIRS TO GBJ 7339B FOR THIRD PARTY CLAIMS.

PARTS REQUIRED	QTY	AMT \$
1) FRONT BUMPER / <i>OR</i>	1	\$ 367.00
2) FRONT RH FENDER / <i>DO</i>	1	\$ 967.00
3) FRONT RH RETAINER / <i>OR</i>	1	\$ 98.00
4) FRONT RH HEADLAMP / <i>OR</i>	1	\$ 637.00
5) FRONT RH SPLASHGUARD / <i>TN</i>	1	\$ 148.00
LIST PRICE TOTAL <i>10</i>		\$ 2,217.00
LESS DISCOUNT <i>25%</i>		\$ 554.25
LIST PRICE TOTAL AFTER LESS		\$ 1,662.75

NETT PRICE TOTAL

\$0.00

TOTAL PARTS COST

\$1,662.75

LABOUR AND MISCELLANEOUS CHARGES

1) TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP & PANEL BEAT & ALIGN.	\$ 600.00
	(3 DAYS)
2) TO PUTTY & SPRAY PAINT FRONT RH FENDER.	\$ 280.00
	(1 PANEL)
3) TO CHECK & RECTIFY WIRING.	\$ 80.00

LABOUR TOTAL

\$ 880.00

TOTAL ESTIMATED REPAIR COST

\$ 2,542.75

2875.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: