

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21012828/KVY3N2**Date:** 21/03/2022**REFERENCE**

Insured/Claimant: ORIENTAL ROYALTY (S) PTE LTD Policy No: DMCVSNW00028492100
Date of Loss: 11/12/2021 Nature of Claim: OD Claim No: SNM21D207237/C01/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD6848L**
Make & Model: FIAT DOBLO CARGO MAXI, 1.6 (M) Engine No: 198A30007175095
Reg. Date: 16/03/2015 (Man. Year: 2014) Chassis No: ZFA26300006185125
Colour: White Odometer: 246392 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$22,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Nexen 4 mm Rear Left Side: Nexen 7 mm
Front Right Side: Nexen 4 mm Rear Right Side: Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,715.00	14,505.00	12,210.00	45.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	814.80	384.30	430.50	52.84
Paintwork Labour	676.75	436.09	240.66	35.56
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,206.55	15,325.39	12,881.16	45.67
Approved Total (Overridden) (S\$)		12,000.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	28,206.55	10,000.00	18,206.55	64.55
+ GST 7.00/7.00% (S\$)	1,974.46	700.00	1,274.46	64.55
Nett Amount (S\$)	30,181.01	10,700.00	19,481.01	64.55

INSPECTION

Date of Assignment: 20/12/2021 Present Location: Ding Auto Pte Ltd (HQ)
Date Inspected: 20/12/2021 Inspected At: BLK 10 #01-20 SIN MING IND EST SEC C
SINGAPORE 575645
Estimated Period of Repair: 7.0 days REPAIRER: DING AUTO PTE LTD

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2022)

Parts: 213 FIAT DOBLO CARGO MAXI 1.6 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBD6848L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TOTAL PARTS		26,715.00 F	*14,505.00 F	
					Total Parts (S\$)	26,715.00	14,505.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	474.60	323.40
2	Total Paint Materials	New	202.15	112.69
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	814.80	384.30
			Gross Labour Cost (\$\$)	1,491.55
				820.39

Report was unsubmitted during this print-out.

< END OF ESTIMATES >