

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk
10,#01-20
575645



Insurer Reference:
Repairer Reference: 045136
Date calculated: 16/12/2021 3:02 PM

Full Report
Registration: GBD6848L
Printed: 16/12/2021 3:03 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:		Date of Incident:	11/12/21
Estimated Repair Time:	21	Hire Car Start:	
Actual Repair Days:	21	Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	FIAT		
Model:	DOBLO VAN		
Sub Model:	BASE MODEL		
Model Sheet Number:	08 AG 01		
Registration:	GBD6848L		
VIN number:			
Odometer:	246392		
Model Specs			
FROM 01.2015	AIR CONDITIONING	LUGGAGE COMP COVER	1.6 LTR 77 KW
GRILLE PLATFORM	PART GLAZED BOX VAN		

Not Authorized
L1Png &
Ex @ 2000.

Fday

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Phunng Alee Pong

Code	Description	WU	Price SGD
7620C60	R + R BONNET		
7620C62	R + R L/BONNET HINGE	4.5	18.90
7620C62	R + R BONNET HINGE	1.0	4.20
7025A58	R + R BONNET STAY	1.0	4.20
5540B38	CHECK AND ADJUST HEADLAMPS	2.0	8.40
NO NUMBER	R + R L/DOOR WINDOW TRIM FRAME	2.0	8.40
NO NUMBER	R + R R/WINDOW FRAME MOULDING	1.0	4.20
7210A36	RENEW LEFT FRONT SIDE MEMBER CLOSING	1.0	4.20
7210A36	RENEW RIGHT FRONT SIDE MEMBER CLOSING	9.5	39.90
7640C05	R + R L/F DOOR	9.5	39.90
7640A05	RENEW L/F DOOR (DOOR REMOVED)	4.0	16.80
7640C80	R + R L/F DOOR ATTACHED PARTS	3.5	14.70
7640C05	R + R R/F DOOR	13.0	54.60
7640A05	RENEW R/F DOOR (DOOR REMOVED)	4.0	16.80
7640C80	R + R R/F DOOR ATTACHED PARTS	3.5	14.70
0010T84	AIR CONDITION DRAIN + REFILL	13.0	54.60
5040A40)	R + R CONDENSER (BUMPER REMOVED)	2.5	10.50
5050A10)	R + R WINDSCREEN WASHER TANK	1.0	4.20
5530B52	R + R BATTERY BRACKET	3.5	14.70
(7)	INCLUDES: R + R BATTERY	2.5	10.50
1088B20)	R + R RADIATOR		
	INCLUDES: R + R FAN AND FAN SHROUD, DRAIN + REFILL COOLING SYSTEM	6.0	25.20
1048B50)	R + R CHARGE AIR COOLER		
1016A10	R + R UPPER ENGINE COVER	4.5	18.90
1008C32)	R + R ENGINE STRUT	1.0	4.20
1088B10)	OVERFLOW TANK FOR COOLANT	2.5	10.50
4130A10)	R + R STEERING GEAR (FRT AXLE BODY REM)	1.0	4.20
4130B58)	R + R COLD WATER PIPE	0.5	2.10
4450C10)	R + R LEFT FRONT STEERING KNUCKLE (WHEEL REMOVED)	3.0	12.60
	INCLUDES: R + R BRAKE DISC AND BRAKE DISC PROTECTION PLATE	6.5	27.30
4450C10)	R + R RIGHT FRONT STEERING KNUCKLE (WHEEL REMOVED)	6.5	27.30
	INCLUDES: R + R BRAKE DISC AND BRAKE DISC PROTECTION PLATE		
4450C14)	R + R FRONT STEERING KNUCKLE ASS WORK	1.0	4.20
50C34)	R + R LEFT FRONT WHEEL BEARING	2.5	10.50
4450C34)	R + R RIGHT FRONT WHEEL BEARING	2.5	10.50
4410B40)	R + R L/F CONTROL ARM (WHEEL REMOVED)	4.5	18.90
4410B40)	R + R R/F CONTROL ARM (WHEEL REMOVED)	4.5	18.90
4410A18)	R + R FRONT SUSPENSION STRUT	2.0	8.40
4410A12)	R + R LEFT FRONT SHOCK ABSORBER/SPRING (SUSPENSION STRUT REMOVED)	4.0	16.80
4410A12)	R + R RIGHT FRONT SHOCK ABSORBER/SPRING (SUSPENSION STRUT REMOVED)	4.0	16.80
4410C10)	R + R FRONT STABILIZER	7.0	29.40
4450C38)	R + R FRONT WHEEL HUB BEARING ADD	1.5	6.30
4410D15)	R + R FRONT AXLE CARRIER	9.0	37.80
4410D17)	R + R FRONT CROSSMEMBER	0.5	2.10

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	19.40	194.0	814.80
Total of Labour			814.80

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description		WU	Price SGD
	BONNET NEW PART PAINTING		19.0	
	L/F WING NEW PART PAINTING		11.0	
	R/F WING NEW PART PAINTING		11.0	
	FRONT PANEL SURFACE PAINT		4.0	
	L/F HEADLAMP BRACKET SURFACE PAINT		4.0	
	R/F HEADLAMP BRACKET SURFACE PAINT		4.0	
	L/R LAMP BRACKET SURFACE PAINT		4.0	
	R/R LAMP BRACKET SURFACE PAINT		4.0	
	L/S-MEMB CLOSING PNL SURFACE PAINT		4.0	
	R/S-MEMB CLOSING PNL SURFACE PAINT		4.0	
	LEFT FRONT DOOR NEW PART PAINTING		18.0	
	RIGHT FRONT DOOR NEW PART PAINTING		18.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	50.38
0741	L/F WING NEW PART PAINTING	18.94
0742	R/F WING NEW PART PAINTING	18.94
0920	FRONT PANEL SURFACE PAINT	2.82
0925	L/F HEADLAMP BRACKET SURFACE PAINT	0.35
0926	R/F HEADLAMP BRACKET SURFACE PAINT	0.35
0927	L/R LAMP BRACKET SURFACE PAINT	0.35
0928	R/R LAMP BRACKET SURFACE PAINT	0.35
0953	L/S-MEMB CLOSING PNL SURFACE PAINT	0.70
0954	R/S-MEMB CLOSING PNL SURFACE PAINT	1.41
1481	LEFT FRONT DOOR NEW PART PAINTING	44.73
1482	RIGHT FRONT DOOR NEW PART PAINTING	44.73

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint	42.00 SGD/h		
Preparation Main Work Metal		105.0	
Total	10 WU/h	11.30	33.60
		113.0	474.60

Material Cost - Paint

	Price SGD
New Part Painting	177.72
Surface-/Blend Paint	6.33
Material-constant Metal	18.10
Total	202.15

Spare Parts

prices as at 2001-01-01

Code	Description	Part Number	Part Source	Price SGD	
0257	FRONT NUMBER PLATE	KNPL3	Original		
0258	FRT NO PLATE REINF	0000735615598	Original	mit 30.00	✓
0283	FRONT BUMPER	0000735615285	Original	su 30.00	X
0285	FRT BUMPER REINF	0000052180630	Original	B 670.00	✓
0293	L/F BUMPER AIR GUIDE	0000735615291	Original	B 485.00	✓
0294	R/F BUMPER AIR GUIDE	0000735615290	Original	CM 120.00	✓
0295	L/F BUMPER PANEL	0000735615288	Original	120.00	?
0296	R/F BUMPER PANEL	0000735615287	Original	185.00	X
0301	FRT BUMPER WIND DEFL	0000051828678	Original	185.00	X
0340	FRONT CROSSMEMBER	0000051984389	Original	90.00	?
0345	FRT BUMPER ABSORBER	0000051974242	Original	485.00	?
0346	R/F BUMPER COVER	0000735615289	Original	CM 180.00	✓
0411	GRILLE	0000735618636	Original	mi 35.00	✓
0431	GRILLE BADGE	0000735578621	Original	CM 245.00	✓
0471	BONNET	0000052101773	Original	u 90.00	✓
0475	L/BONNET HINGE	0000052035197	Original	Bu 650.00	✓
0476	R/BONNET HINGE	0000052035196	Original	B 70.00	✓
0485	BONNET INSULATION	0000051890148	Original	B 70.00	✓
0493	BONNET LOCK	0000052046011	Original	Reform 185.00	✓
0495	BONNET STAY	0000052027740	Original	Tan 105.00	✓
0497	L/F BUMP CORNER BRKT	0000051973269	Original	55.00	?
0498	R/F BUMP CORNER BRKT	0000051973268	Original	CM 70.00	✓
0528	FRONT BONNET SEAL	0000051987095	Original	CM 70.00	✓
0531	LEFT BONNET STOP	0000046456562	Original	120.00	?
0532	RIGHT BONNET STOP	0000046456562	Original	25.00	?
0561	LEFT HEADLAMP ASSY	0000052109260	Original	25.00	?
0562	RIGHT HEADLAMP ASSY	0000052109257	Original	Ro 375.00	✓
0741	L/F WING	0000051973882	Original	My Au 375.00	✓
0742	R/F WING	0000051973881	Original	B 430.00	✓
0745	L/F WING BRACKET	0000051810995	Original	Bu 430.00	✓
0746	R/F WING BRACKET	0000051811090	Original	75.00	?
0841	L/F WHEELHOUSE COVER	0000052128357	Original	75.00	?
0842	R/F WHEELHOUSE COVER	0000052128361	Original	CM 145.00	✓
0920	FRONT PANEL	0000052122658	Original	145.00	?
0925	L/F HEADLAMP BRACKET	0000051974123	Original	Bu 320.00	✓
0926	R/F HEADLAMP BRACKET	0000051974118	Original	160.00	?
0927	L/R LAMP BRACKET	0000051974099	Original	160.00	?
0928	R/R LAMP BRACKET	0000051973089	Original	35.00	?
0953	L/S-MEMB CLOSING PNL	0000052007755	Original	35.00	?
0954	R/S-MEMB CLOSING PNL	0000052007753	Original	90.00	?
1385	L/COWL MOULDING	0000735498423	Original	90.00	?
1386	R/COWL MOULDING	0000735498422	Original	55.00	?
1393	COWL PANEL GRILLE	0000735498287	Original	55.00	?
1395	REAR BONNET SEAL	0000052018491	Original	CM 180.00	✓
1435	WASHER RESERVOIR	0000052046691	Original	150.00	?
1481	LEFT FRONT DOOR	0000052155068	Original	120.00	?
1482	RIGHT FRONT DOOR	0000052155064	Original	R 1,250.00	X
1525	L/F DOOR REP KIT	SEE GUIDE NO. 1537		R 1,250.00	X
1526	R/F DOOR REP KIT	SEE GUIDE NO. 1538			
1537	L/SCREW	0000018754324		0.00	
1538	R/SCREW	0000018754324		0.00	

Code	Description	Part Number	Part Source	Price SGD
4465	AIR CON CONDENSER	0000051937924	Original	815.00
7011	FRONT AXLE BEAM	0000052078744	Original	X2,150.00
7025	LWR AXLE MEMB REINF	0000051974659	Original	X 245.00
7053	L/F TRACK CONT ARM	0000051932035	Original	170.00
7054	R/F TRACK CONT ARM	0000051932036	Original	170.00
7077	L/FR SHOCK ABSORBER	0000052093954	Original	170.00
7078	R/FR SHOCK ABSORBER	0000052093961	Original	170.00
7081	L/F STEERING KNUCKLE	0000052043100	Original	645.00
7082	R/F STEERING KNUCKLE	0000052043098	Original	645.00
7099	L/F S-ABS BRKT	0000052208017	Original	70.00
7100	R/F S-ABS BRKT	0000052208016	Original	70.00
7117	L/F WHEEL BEARING	0000046836196	Original	275.00
7118	R/F WHEEL BEARING	0000046836196	Original	275.00
7131	L/F WHEEL HUB	0000052017379	Original	230.00
7132	R/F WHEEL HUB	0000052017379	Original	230.00
7261	FRONT STABILISER	0000051886184	Original	415.00
7277	L/F STABI LINKAGE	0000052042281	Original	75.00
7278	R/F STABI LINKAGE	0000052042281	Original	75.00
7300	STEERING GEAR ASSY	USE SINGLE PARTS	Original	4,150.00
7311	L/OUTER TIE ROD BALL	0000077365223	Original	110.00
7312	R/OUTER TIE ROD BALL	0000077365224	Original	110.00
7480	POWER STEERING PIPE	0000051952538	Original	180.00
7761	RADIATOR	0000051897080	Original	565.00
7763	INTERCOOLER	0000051833975	Original	1,250.00
7765	RADIATOR AIR GUIDE	0000051974448	Original	235.00
7767	UPPER AIR GUIDE	0000051974446	Original	120.00
7787	EXPANSION TANK	0000051824339	Original	145.00
7790	FAN/FAN SHROUD CPL	0000051833973	Original	185.00
8780	LOWER ENGINE PROTECT	0000051844337	Original	670.00
8782	R/ENGINE COVER	0000051832930	Original	85.00
9646	HIGH TONE HORN	0000052090834	Original	120.00
1000	AIR CLEANER BOX	AIR CLEANER BOX	Original	710.00
1001	AIR INTAKE DUCT	AIR INTAKE DUCT	Original	160.00
1002	RADIATOR FAN ASSY	RADIATOR FAN	Original	495.00
1003	BUMPER SPONGE FOAM	BUMPER FOAM	Original	135.00
				0.00
f: OEM Parts	Savings			
n: Non-OEM Parts	Subtotal			26,715.00
u: Used parts	Total			26,715.00

Final Calculation

	SGD	SGD
parts		
Total Parts	26,715.00	26,715.00
Labour Time Base 10 WU/h		
Total 194.0 WU X 42.00 SGD/h	814.80	814.80
Paint Work Time Base 10 WU/h		
Labour Cost 113.0 WU X 42.00 SGD/h	474.60	
Material Cost	202.15	
Total Paint Including Material		676.75
Repair Cost Excludes GST		28,206.55
GST (+7.0%)		1,974.46
Repair Cost Included GST		30,181.01

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.