

⏪

⏩

1 of 2 ?

⏴

⏵

100%

⏴

⏵

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref: CS3/EQI21012829/Gqf3	
5 MAXWELL ROAD			Date: 20/12/2021	
#17-00 TOWER BLOCK				
MND COMPLEXSINGAPORE 069110			Code: EQI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBN 5716M	Veh. Inspected	SLW 4066X	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM21HO01872/JT	Excess (\$)	0.00	
Assign From	JAIME TAY	Assign Date	20/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/12/2021	Inspection Date	21/12/2021	
Survey held at	2 Kaki Bukit Avenue 2 #02-21 Kaki Bukit Autohub			
Repairer	KIM SIA AUTO SERVICE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				