


Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Cheng Ltor  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. SNM21D207373/C02  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 06 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBC 5517D Yr Regn: 01, 13  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or (A) Printer 316001 2143  
 Make: Mer  
 Colour: Yellow A/C: Insured / Std / NI / NA  
 Sp. Reading: 113571 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDB 90663325718047  
 Gen. Cond: Good Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modl: NII S/Rlm / STD A/Rlm or  
 Tyre Size: Continental  
R: Humko 235/65R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front Rear  
 R/Bal. 7 mm R/Bal. 9 mm  
 L/Bal. 7 mm L/Bal. 9 mm  
 D.O.A. 17/12/21 D.O.I. 20/12/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear & n/s body  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/01/22@12.41pm revised to Pauline Tham via Merimen.

Kenneth confirmed L.S. \$4200 (Red \$2564, 38%)

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 6

1) 25/01 Typist

☐ : Final ReportResurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

S + RS \$ \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_)

Fees

☐ : Tech Invs (\$ \_\_\_\_\_)

Others

☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

Report Format: MER-TP

Lump Sum / L.S. (\$ 4200)

# REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 18 Dec 2021)  
 Parts: N/A MERCEDES-BENZ 316CDI/3665 2.1 (A) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for GBC5517D)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

GBC5517D  
TP/CHINA

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	Re *395.00 F ✓
2	1		*1 PC REAR BUMPER RH REFLECTOR	0.00	0.00	Br *12.00 F ✓
3	1		*1 PC REAR BUMPER RH SIDE PAD	0.00	0.00	Rt *110.00 F ✓
4	1		*1 PC REAR BUMPER REINFORCEMENT	0.00	0.00	*460.00 F ?
5	1		*2 PCS REAR BUMPER TOP CLIPS @3/PC	0.00	0.00	Re *6.00 F ✓
6	1		*1 PC REAR BUMPER RH TOP PROTECTOR	0.00	0.00	Re *20.00 F ✓
7	1		*1 PC RH TAILLAMP COVER	0.00	0.00	*185.00 F ?
8	1		*1 PC RH TAILLAMP HOUSING	0.00	0.00	Re *230.00 F ✓
9	1		*1 PC RH TAILLAMP SOCKET	0.00	0.00	Re *39.00 F ✓
10	1		*3 PCS RH TAILLAMP CLIPS @3/PC	0.00	0.00	Re *9.00 F ✓
11	1		*1 PC RH TAILGATE	Re 0.00	0.00	*1,450.00 F ✓
12	1		*1 PC RH TAILGATE LOWER HINGE	0.00	0.00	Re *165.00 F X
13	1		*1 PC RH TAILGATE INNER RUBBER	Re 0.00	0.00	*230.00 F ✓
14	1		*1 PC RH TAILGATE EMBLEM (316 CDI)	0.00	0.00	Re *105.00 F ✓
15	1		*1 PC LH TAILGATE EMBLEM (SPRINTER)	0.00	0.00	Re *88.00 F ✓

F=Franchise part.

Total Parts (\$\$) 3,504.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS


## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC STICKER - 70KM.H	Re 10.00 ✓
Sub Total (\$\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, BUMPER SIDE PAD, RH TAILGATE, LOCK ASSY, TO CUT, WELD & RENEW RH TAILLAMP PANEL, KNOCK & REPAIR REAR RH SIDE PANEL, LH SIDE PANEL, REAR END PANEL, REAR RH CORNAL FLOOR BOARD AND REALIGN THE SAME	New	800 1,000.00
2	PUTTY & RESPRAY ON RH & LH TAILGATE, BOTH SIDE PANELS, TAILLAMP PANEL AND REAR RH CORNAL FLOOR BOARD PANEL & ALL AFFECTED AREAS	New	1,000 1,200.00
3	TO REWRITE ADVERTISEMENT	New	(Bill) 800.00 ?
4	RUSTPROOFING	New	30.00 ✓
Gross Labour Cost (\$\$)			3,030.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS



# CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

--

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(SMU6931J)
Policy No:		Date of Loss:	17/12/2021
Vehicle Reg. No.:	GBC5517D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	PHUA MING HONG	Driver (Insured):	LEE WEI NENG

Make/Model:	MERCEDES-BENZ 316CDI/3665, 2.1 (A)	Vehicle Reg. Date:	22/01/2013
Vehicle Colour:	YELLOW		
Engine No:	65195531279705	Chassis No:	WDB9066332S718047
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		

*Not authorized  
L1 Rep &  
Repair after 6 days*

Description of Accident/Loss: REFER TO GIA REPORT ATTACHED.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

## COST OF CLAIMS

Parts	• To resurvey before/after spray painting	3,504.00
Miscellaneous Items	• To display damaged part(s) during resurvey	10.00
Labour	• Parts prices are subject to confirmation	3,030.00
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	0.00
Towing	• No illegal modification(s) is allowed	0.00
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	0.00
Gross Total (S\$)		6,544.00
+ GST 7.00% (S\$)		458.08
Nett Amount (S\$)		7,002.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 17/12/2021 19:20 (SGT)  
Date of Accident ..... 17/12/2021 07:45 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... INFRONT OF #01-260,BLK 1017 YISHUN IND PARK A  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... GBC5517D

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... WELTUNE AUTO SERVICES  
Company Reg No ..... 3XXXX100D  
Email Address ..... phuaminghong@gmail.com  
Mobile Phone No ..... (Phone) +65-91129916  
Alternative Phone No ..... +65-91129916

### VEHICLE PARTICULARS

Manufacturer ..... Mercedes  
Model ..... 316CDI/3665  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Employment  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Motor trade  
Transmission ..... Manual  
CC ..... 2143

### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... ThirdParty  
Fleet Policy ..... No  
Policy Number ..... 5122176519  
Cover Note Number ..... 17/5/21-16/5/22

### DRIVER

Name of Driver ..... PHUA MING HONG  
NRIC No ..... SXXXX113J




A = GBC 5517D  
 B = SMU 6931J  
 Lee Wei Neng  
 SS 817790H  
 HP: 8788 3011

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

DOA: 17/12/21 Time: 0745hrs. HP: 8788 3011

m/van (A) was parked stationary in front of our premise #01-260. Our neighbour called us to inform that a m/car (B) had collided onto van (A).

We came to scene and found our van (A) was pushed to the left and hit onto container/barrel on the left. The driver of car (B) waited for us and had provided his particulars.



**Note :** Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

( ) Claim Own Policy ( / ) Claim Third Party ( ) Reporting Only  
 ( ) Claim OD/TP at other workshop ( )

17/12/21