

|              |                                      |
|--------------|--------------------------------------|
| Claim        | S1M03MP9                             |
| Reference    | CS/ASM21012839/Kty3e2                |
| Loss Date    | 21 November 2021                     |
| Vendor Name  | LKK AUTO CONSULTANTS<br>PTE LTD (TP) |
| Type of Loss | Third Party Vehicle Damage           |
| Report Date  | 23 Nov 2021 1:19:25 PM               |
| Request Date | 20 December 2021                     |
| Due Date     |                                      |
| Services     | Re-inspection                        |

### Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

|                |              |
|----------------|--------------|
| Incident       | SMF3084C     |
| Vehicle        |              |
| Registration # |              |
| Make           | TPVD UNKNOWN |
| Model          | UNKNOWN      |

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Service Requests

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

| NAME                                                                                                                                 |                     | DATE UPLOADED              |                                   |                |
|--------------------------------------------------------------------------------------------------------------------------------------|---------------------|----------------------------|-----------------------------------|----------------|
| NAME                                                                                                                                 | TYPE                | SUBTYPE                    | AUTHOR                            | DATE UPLOADED  |
|  <a href="#">ASM_LKKInvoice_AC2108970.pdf.pdf</a> | Email Sent          | Surveyor/ Assessor expense | LKK AUTO CONSULTANTS PTE LTD (TP) | 3 January 2022 |
|  <a href="#">LKKInspection.pdf.pdf</a>            | Reports & Statement | Survey Report              | LKK AUTO CONSULTANTS PTE LTD (TP) | 3 January 2022 |

| FAQ English (SG) Elaine Kuan                                                                                                                                                                                              |                                                                                                                                                                      |  | TYPE                          | SUBTYPE                                      | AUTHOR                                  | DATE<br>UPLOADED       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------------|----------------------------------------------|-----------------------------------------|------------------------|
|  <div> <div>Service Requests</div> <div>  </div> </div> |                                                                                                                                                                      |  | Reports &<br>Statement        | Survey Report                                | LKK AUTO<br>CONSULTANTS PTE<br>LTD (TP) | 3 January<br>2022      |
|                                                                                                                                                                                                                           |  LKKPhoto.pdf.pdf                                                                   |  | Evidence                      | Photos                                       | LKK AUTO<br>CONSULTANTS PTE<br>LTD (TP) | 3 January<br>2022      |
|                                                                                                                                                                                                                           |  EMAIL TO LKK ON REINSPN.msg.msg                                                    |  | Letters and<br>Correspondence | Surveyor / Assessor                          | OH Vale                                 | 20<br>December<br>2021 |
|                                                                                                                                                                                                                           |  TP LOD LITIGATION - REUTENS SHARON<br>SANDRA-VISION LAW LLC - KIV 18.01.21.msg.msg |  | Legal                         | Letter of<br>Demand/Notice of<br>Proceedings | VISHNU BATHAM<br>Shekhar                | 16<br>December<br>2021 |
|                                                                                                                                                                                                                           |  TP LOD LITIGATION ACK- REUTENS SHARON<br>SANDRA.msg.msg                          |  | Legal                         | Letter of<br>Demand/Notice of<br>Proceedings | VISHNU BATHAM<br>Shekhar                | 16<br>December<br>2021 |
|                                                                                                                                                                                                                           |  SMF3084C DISMANTLE AND DAMAGED PHOTOS<br>1.png.png                               |  | Other                         | Other                                        | VICOM LTD (TP)<br>(DC)                  | 8<br>December<br>2021  |

| FAQ English (SG) Elaine Kuan                                                                                                            |                                                                                                                    |  | TYPE                   | SUBTYPE       | AUTHOR                 | DATE<br>UPLOADED      |
|-----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|--|------------------------|---------------|------------------------|-----------------------|
|  <div>Service Requests</div> <div>PAINT2.png.png</div> | ...                                                                                                                |  | Other                  | Other         | VICOM LTD (TP)<br>(DC) | 8<br>December<br>2021 |
|                                                                                                                                         |  SMF3084C DAMAGED PHOTOS1.png.png |  | Other                  | Other         | VICOM LTD (TP)<br>(DC) | 8<br>December<br>2021 |
|                                                                                                                                         |  SMF3084C MV.pdf.pdf              |  | Reports &<br>Statement | Survey Report | VICOM LTD (TP)<br>(DC) | 8<br>December<br>2021 |
|                                                                                                                                         |  Dismantle14.jpg.JPG              |  | Reports &<br>Statement | Survey Report | VICOM LTD (TP)<br>(DC) | 8<br>December<br>2021 |
|                                                                                                                                         |  DSC_0001.jpg.JPG               |  | Reports &<br>Statement | Survey Report | VICOM LTD (TP)<br>(DC) | 8<br>December<br>2021 |
|                                                                                                                                         |  DSC_0003.jpg.JPG               |  | Reports &<br>Statement | Survey Report | VICOM LTD (TP)<br>(DC) | 8<br>December<br>2021 |

| FAQ English (SG) ▼ Elaine Kuan ▼                                                                                             |                                                                                                         |  | TYPE                | SUBTYPE       | AUTHOR              | DATE<br>UPLOADED      |
|------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|--|---------------------|---------------|---------------------|-----------------------|
|  <div>Service Requests</div> <div>...</div> |                                                                                                         |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle3.jpg.JPG    |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle13.jpg.JPG   |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle9.jpg.JPG    |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle12.jpg.JPG |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle10.jpg.JPG |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |

| FAQ English (SG) ▼ Elaine Kuan ▼                                                                                             |                                                                                                         |  | TYPE                | SUBTYPE       | AUTHOR              | DATE<br>UPLOADED      |
|------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|--|---------------------|---------------|---------------------|-----------------------|
|  <div>Service Requests</div> <div>...</div> |                                                                                                         |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle.jpg.JPG     |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle8.jpg.JPG    |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle4.jpg.JPG    |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle7.jpg.JPG  |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  Dismantle11.jpg.JPG |  | Reports & Statement | Survey Report | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |

| FAQ English (SG) ▼ Elaine Kuan ▼                                                                                             |                                                                                     |                                                  | TYPE                | SUBTYPE                    | AUTHOR              | DATE<br>UPLOADED      |
|------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------|---------------------|----------------------------|---------------------|-----------------------|
|  <div>Service Requests</div> <div>...</div> |                                                                                     |                                                  | Reports & Statement | Survey Report              | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |    | <a href="#">SMF3084C SURVEYOR REPORT.pdf.pdf</a> | Reports & Statement | Survey Report              | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |    | <a href="#">CL025602 SMF3084C.pdf.pdf</a>        | Email Sent          | Surveyor/ Assessor expense | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |    | <a href="#">SMF3084C Photos 2.pdf.pdf</a>        | Evidence            | Photos                     | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  | <a href="#">SMF3084C Photos 1.pdf.pdf</a>        | Evidence            | Photos                     | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |
|                                                                                                                              |  | <a href="#">SMF3084C Dismantle.pdf.pdf</a>       | Evidence            | Photos                     | VICOM LTD (TP) (DC) | 8<br>December<br>2021 |

| FAQ English (SG) ▼ Elaine Kuan ▼                                                                             |                                                                                   |                                         | TYPE                   | SUBTYPE    | AUTHOR  | DATE<br>UPLOADED       |
|--------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------|------------------------|------------|---------|------------------------|
| <br>Service Requests<br>... |  | <a href="#">INSRD GIA REPOT.pdf.pdf</a> | Reports &<br>Statement | GIA Report | OH Vale | 24<br>November<br>2021 |
|                                                                                                              |                                                                                   |                                         | Reports &<br>Statement | GIA Report | OH Vale | 24<br>November<br>2021 |