

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

GUI AH BAH
30 JALAN PARI UNAK
SINGAPORE 488503

78 AXA.
Asher.

TAX INVOICE

Repair Code : CLM15378

Date in : 18/12/2021

Vehicle Num. : SJB4761G

Model : TOYOTA VIOS J AUTO

Chassis/Eng# : MR053HY9305046508/1NZX689636

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Ry's</i>	1	666.70	666.70 <i>x</i>
REAR BOOTLID 'J' EMBLEM	1	51.10	51.10 <i>✓</i>
REAR BOOTLID 'LOGO' EMBLEM	1	53.90	53.90 <i>✓</i>
REAR BOOTLID 'VIOS' EMBLEM	1	51.50	51.50 <i>✓</i>
REAR BOOTLID HINGES L/R <i>2 New</i>	2	59.50	119.00 <i>x</i>
REAR BOOTLID MECHANISM LOCK	1	106.40	106.40 <i>x</i>
REAR BOOTLID RUBBER GUIDE STOPPER L/R <i>New</i>	2	23.90	47.80 <i>x</i>
REAR BOOTLID WEATHER STRIP <i>1x</i>	1	194.20	194.20 <i>✓</i>
REAR BUMPER <i>Distorted</i>	1	495.70	495.70 <i>✓</i>
REAR BUMPER LH BRACKET <i>3x</i>	1	69.90	69.90 <i>✓</i>
REAR BUMPER LH END SEAL COVER <i>seal torn</i>	1	55.50	55.50 <i>✓</i>
REAR BUMPER REFLECTOR L/R <i>LH cracked</i>	2	92.00	184.00 <i>92</i>
REAR BUMPER SIDE CORNER BRACKET L/R <i>New</i>	2	39.80	79.60 <i>x</i>
REAR BUMPER SIDE RETAINER L/R <i>LH cracked</i>	2	102.80	205.60 <i>102.80</i>
REAR END PANEL <i>Dented</i>	1	696.30	696.30 <i>✓</i>
REAR END PANEL INNER TOP GARNISH <i>cracked</i>	1	222.80	222.80 <i>✓</i>
REAR LH FENDER <i>Buckled</i>	1	1051.90	1,051.90 <i>✓</i>
REAR LH FENDER AIR VENT <i>dehnd</i>	1	136.80	136.80 <i>✓</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

GUI AH BAH
 30 JALAN PARI UNAK
 SINGAPORE 488503

Contact : 94519611, 91253132

TAX INVOICE

Repair Code : CLM15378

Date in : 18/12/2021

Vehicle Num. : SJB4761G

Model : TOYOTA VIOS J AUTO

Chassis/Eng# : MR053HY9305046508/1NZX689636

REAR LH FENDER INNER UPHOLSTERY TRIM GARNISH <i>new</i>	1	247.90	247.90	<i>f</i>
REAR LH FLOOR SIDE PANEL <i>Buch d</i>	1	138.70	138.70	<i>✓</i>
REAR LH SPARE TYRE TOP SPONGE <i>crushed</i>	1	190.00	190.00	<i>✓</i>
REAR LH TAILLAMP <i>crushed</i>	1	342.40	342.40	<i>✓</i>
REAR LH TAILLAMP PANEL <i>Buch d</i>	1	231.20	231.20	<i>✓</i>
REAR SPARE TYRE INNER TOP CARDBOARD COVER <i>torn</i>	1	132.70	132.70	<i>✓</i>
REAR TAILLAMP BACK RUBBER GASKET L/R <i>LH new</i>	2	61.10	122.20	<i>20</i>
REAR WINDSCREEN GLASS MOULDING <i>new</i>	1	89.20	89.20	<i>✓</i>
REAR WINDSCREEN GLASS SEAL <i>new</i>	1	43.00	43.00	<i>✓</i>
Subtotal before discount			6,026.00	
Percentage discount 25%			1,506.50	
Sub-total 1			4,519.50	
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00	<i>130</i>
REAR BUMPER LH END SEAL COVER CLIPS - SET <i>new</i>	1	30.00	30.00	<i>10</i>
REAR BUMPER REVERSE SENSOR - SET <i>new</i>	1	250.00	250.00	<i>20</i>
REAR END PANEL GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00	<i>10</i>
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	60.00	<i>5</i>
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	60.00	<i>10</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

GUI AH BAH
30 JALAN PARI UNAK
SINGAPORE 488503

Contact : 94519611, 91253132

TAX INVOICE

Repair Code : CLM15378

Date in : 18/12/2021

Vehicle Num. : SJB4761G

Model : TOYOTA VIOS J AUTO

Chassis/Eng# : MR053HY9305046508/1NZX689636

REAR WINDSCREEN GLASS SEALANT <i>Neu</i>	1	80.00	80.00 <i>60</i>
	Subtotal before discount		560.00
Percentage discount 0%			0.00
	Sub-total 2		560.00
	Parts-total		5,079.50

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove and refit rear windscreen(to FR)

To remove, reinstall petrol tank. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

60.00 *50*
150.00 *120.*
80.00 *✓*
140.00 *80.*
1,500.00 *1200*
2,000.00 *1300*
120.00 *80.*
4,050.00
9,129.50

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/s 21/12/21.

08 Days.

total: 6576.20

L/s: S-21C ✓