FORT TRANSPORTATION PTE LTD

AIR ESTIMATE

hicle No. : SHC2777T

ake : HYUNDAI

lodel : IONIQ(G2)

Date: 18/12/2021

Insurance: AIG

MVA: MS. LOKE YY

		WWW.EGILETT		
Qty	Parts Description / Labour	Туре	Unit Price	Amount
	REAR BUMPER COVER REAR BUMPER CLIPS			NY\$459.40
	REAR BUMPER CENTRE MOULDING ASSY			di \$451.25
	REAR BUMPER REINFORCEMENT		N	\$394.80
	REAR BUMPER LOWER CTR MOULDING		an	\$155.00
	ANTENNA SMARTKEY	.'		CM \$40.50
	REAR BUMPER FOG LAMP			M \$ \$201.50
	LICENCE LAMP			J \$85.30
	EICENCE LAWIF			X 400.01
	SUB TOTAL		666 AS	\$1,482.4
	LESS 20%		668 .75	\$296.4
	DISCOUNTED TOTAL		535	\$1,185.9
11	REAR BUMPER RUBBER MAT			NN K \$50.0
ľ	REAR NUMBER PLATE WITH TRIM COVER		An	an \$55.0
	REAR BUMPER REVERSE SENSOR		225	m \$180.0
1			235	\$235.
	Labour Charge			350 \$400
1	PANEL BEATING			10 0 P400.
	SPRAY PAINTING CHARGE		660	\$300.
C	CHECK ALL LIGHTING			30 \$60.
F	REMOVE/REFIX REVERSE SENSOR			J⊃ \$80.
	TOTAL LABOUR		11430	\$840.
	ESTIMATE TOTAL		Odasi	\$2,260
	ESTIMATE TOTAL	1	1 Zoungs	\$2,200
			γ')	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Toufill 97415749

WY 20/12/21 (2525

M Resumy new pands

2 days

tayfilm Chitandown

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: