

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBE2352X

Model:

NISSAN NV 350

Accident Date : 18/12/2021

JN1MC2E2620005049

29/9/2015

Location : PIE TOWARDS CHANGI BEFORE UPPER SERANGOON EXIT

3P:

GBB7208M (ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>rehd</i>			796.20
2	2 pcs	Rear bumper o/s & n/s corner clips <i>re</i>		40.00	20
3	10 pcs	Rear bumper clips <i>re</i>			30.00
4	3 pcs	Rear bumper center bracket <i>re</i>			80.00
5	2 pcs	Rear bumper o/s & n/s retainer <i>re</i>			246.20
6	1 set	Rear bumper reverse sensor <i>Dmgd</i>		280.00	20
7	1 pc	Rear tail-gate <i>Distrd</i>			2,200.40
8	1 pc	Rear tail-gate weatherstrip <i>dist int</i>			286.10
9	1 pc	Rear tail-gate 'NISSAN' emblem <i>?</i>			86.70
10	1 pc	Rear tail-gate 'NV350' emblem <i>re</i>			106.70
11	1 pc	Rear tail-gate '70KMPH' emblem		15.00	✓
12	1 pc	Rear tail-gate lock (upper) <i>Dmgd</i>			268.40
13	1 pc	Rear tail-gate lock (lower) <i>re</i>			136.10
14	1 pc	Rear lock actuator <i>Dmgd</i>			355.60
15	1 pc	Rear wiper motor <i>gnt</i>			310.20
16	1 pc	Rear wiper <i>re</i>		60.00	+
17	1 pc	Rear tail-gate moulding (chrome) <i>crnd</i>			586.20
18	6 pcs	Rear tail-gate moulding (chrome) clips <i>re</i>		12.00	✓
19	1 pc	Rear tail-gate inner trim <i>horn</i>			266.10
20	12 pcs	Rear tail-gate inner trim clips <i>re</i>		36.00	20
21	2 pcs	Rear tail-gate o/s & n/s shock absorber <i>?</i>			468.00
22	2 pcs	Rear tail-gate o/s & n/s hinges <i>re</i>			368.00
23	2 pcs	Rear tail-gate o/s & n/s rubber stopper			40.00
24	1 pc	Rear tail-gate floor plywood <i>re</i>		450.00	+
25	1 pc	Rear end panel outer <i>Dented</i>			584.80
26	1 pc	Rear end panel step panel <i>Bent</i>			234.60
27	1 pc	Rear end panel top garnish chrome <i>Bent</i>			140.00
28	2 pcs	Rear o/s & n/s tail-lamp <i>crnd</i>			697.20
29	2 pcs	Rear o/s & n/s tail-lamp panel <i>Rejs</i>			846.40
30	1 pcs	Rear o/s body panel <i>Rejs</i>			1,867.80

31	1pcs	Rear rear view mirror <i>new</i>			250.00	+
32	1 pc	Rear windscreen moulding <i>7pc</i>		80.00	✓	
33	1 pc	Rear windscreen sealant		60.00	✓	
34	1 pc	Rear windscreen <i>Shattered</i>			954.60	✓
35	2 pcs	Rear reg. no. plate lamp <i>new</i>			166.00	+
36	1 pc	Rear reg. no. plate <i>Bent</i>		45.00	30	
37	1 pc	Front bumper <i>2 Behind</i>			743.60	✓
38	2 pcs	Front bumper o/s & n/s retainer <i>new</i>			232.40	94. +
39	2 pcs	Front bumper o/s & n/s fog lamp <i>3pc</i>			540.00	+
40	2 pcs	Front bumper o/s & n/s fog lamp bracket <i>3pc</i>			146.40	+
41	1 pc	Front panel <i>dent</i>			1,396.40	✓
42	2 pcs	Front o/s & n/s headlamp <i>could</i>			1,042.60	✓
43	1 pc	Front grille middle (chrome) <i>could</i>			823.50	495. +
44	6 pcs	Front grille middle clips <i>new</i>		18.00		
45	1pc	Front grill lower <i>7pc</i> <i>11003.50 S/N 455</i>			296.50	+
46	6 pcs	Front grill lower clips <i>990315</i>		18.00	+	
47	1 pc	Front regn. no. plate <i>new</i>		45.00	1	
Sub-Total:			0.00	1,159.00	17,593.70	
			30%	0%	10%	
After Less %:			0.00	1,159.00	15,834.33	
Labour						
1		To dismantle damaged portion, straighten & welding.		1,600.00	1400.	
2		To spray painting.		1,400.00	1200.	
3		To remove & replace rear windscreen.		160.00	120.	
4		To remove & replace rear reverse sensor.		80.00	50.	
5		To remove and replace rear tail-gate <i>fitting</i>		120.00	80	
6		To check wiring.		80.00	60	
7		To re-seal anti-rust.		80.00	✓	
Sub-Total:				3,520.00		
Total:				20,513.33		
After Less 20%:				16,410.66		


Chan

23629.04

Adrian L
20/12/21 C/S.

12 days.

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call

Mobil 1



Supplementary: 805.68

total: 14153.83
A/S: 11.31c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 41792

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : GBE2352X

Model:

NISSAN NV 350

Accident Date : 18/12/2021

29/9/2015

Location : FIE TOWARDS CHANGI BEFORE UPPER SERANGOON EXIT

3P:

GBB7208M (ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear Carpet <i>Not new</i>			300.00
2	1 pc	Rear boot floor panel <i>Reps</i>			1,933.10
3	1 pc	Rear tailgate inner trim <i>torn</i>			145.60
4	1 pc	Rear lock cover <i>Not new</i>			58.00
5	1 pc	Spare wheel tyre bracket <i>Good</i>			289.60
6	1 pc	Spare wheel tyre bracket garnish <i>new</i>			110.20
7	1 pc	Rear end panel inner <i>Reps</i>			625.40
Sub-Total:			0.00	0.00	3,461.90
			30%	0%	10%
After Less %:			0.00	-	3,115.71
Total:				3,115.71	
After Less 20%:				2,492.57	

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

*Supplementary: 895.20
805.68*



8778 1999
24 hr accident call

Mobil 1

