

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305498349
Date : 18.12.21
Time of Fax : ✓

Via Fax : EMAIL
Your Insured : SLL 2661Z
Date of Acc : 09.12.2021

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 9430H

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **chianglc@cdge.com.sg**
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully



For Vice President
Taxi Accident Repair

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA9430H

09/12/21

MAKE REG. 02.07.2019

MODEL IONIQ G4

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
1	REAR BUMPER LOWER CENTRE MOULDING			\$155.00
1	REAR CENTRE UNDER COVER			\$225.00
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	BOOTLID COVER			\$2,480.40
1	BOOTLID LOCK UPPER			\$224.00
1	BOOTLID H EMBLEM			\$38.00
1	BOOTLID EMBLEM IONID			\$31.80
1	BOOTLID EMBLEM HYBRID			\$24.30
1	REAR END PANEL			\$532.00
1	REAR PANEL GARNISH			\$346.80
1	BUMPER FOG LAMP			\$201.00
2	BUMPER NUMBER LAMP LH/RH		\$85.30	\$170.60
1	BUMPER HOOK COVER			\$94.60
2	REAR REFLECTOR LH /RH		\$41.45	\$82.90
1	REAR ANTENNA – SMART KEY			\$40.50
2	REAR BUMPER BRACKET LH /RH		\$55.80	\$111.60
				\$6,362.15
	20.00%			\$1,272.43
	DISCOUNTED TOTAL			\$5,089.72
1	BOOTLID ADVERTISEMENT			\$100.00
1	REAR FENDER ADVERTISEMENT LH/RH			\$200.00
1	BOOTLID COMFORT APP STICKER			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00
1	REAR NUMBER PLATE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR			\$180.00
				\$635.00
	Labour Charge			
	Panel Beating			\$900.00
	Spray Painting Charge			\$700.00
	Remove/Refix rear wscreen and lower glass			\$180.00
	Check wiring and lighting			\$60.00
	Tuff Kote			\$60.00
	Remove/Refix reverse sensor			\$60.00
	TOTAL LABOUR			\$1,960.00
	+			
	ESTIMATE TOTAL			\$7,684.72



**SINGAPORE
POLICE FORCE**



T/20211211/2058

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 3

Report No. T/20211211/2058

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/12/2021 16:17		Vide Report No.:		Station Diary No.: 53	
Informant's Particulars					
Name of Informant: HUNG MOW SHING ANTHONY			Address: APT BLK 670C EDGEFIELD PLAINS #02-644 SINGAPORE 823670		
ID Type / ID No.: NRIC NO / S1302189I			Contact No.: Home/Office: Mobile: 81299955		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 04/12/1958	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 09/12/2021 11:10	Type of Location: Straight Road
Location: PAN-ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA9430H	Car		Hyundai AE Ioniq	Yellow	Slightly Damaged	1
SLL2661Z	Car		Mitsubishi Attrage	Red	Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20211211/2058

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 3

Report No. T/20211211/2058

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report

F /

Other LOW SIANG HENG,
JONATHAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/12/2021 16:17

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MUHAMMAD NOOR BIN ABDUL
RAHMAN

Contact No.: 65476201

Classification Of Case:



**SINGAPORE
POLICE FORCE**
SAFEGUARDING EVERY DAY

SN 158

SIGNATURE