

REPAIR ESTIMATE*

09/12/21

MODEL	IONIQ G4
-------	----------

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER STAY LH /RH		LH ? \$138.10	\$276.20
1	REAR BUMPER LOWER CENTRE MOULDING			\$155.00
1	REAR CENTRE UNDER COVER			\$225.00
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	BOOTLID COVER			\$2,480.40
1	BOOTLID LOCK UPPER			\$224.00
1	BOOTLID H EMBLEM			\$38.00
1	BOOTLID EMBLEM IONID			\$31.80
1	BOOTLID EMBLEM HYBRID			\$24.30
1	REAR END PANEL			\$532.00
1	REAR PANEL GARNISH			\$346.80
1	BUMPER FOG LAMP			\$201.00
2	BUMPER NUMBER LAMP LH/RH		\$85.30	\$170.60
1	BUMPER HOOK COVER			\$94.60
2	REAR REFLECTOR LH /RH		\$41.45	\$82.90
1	REAR ANTENNA – SMART KEY			\$40.50
2	REAR BUMPER BRACKET LH /RH		\$55.80	\$111.60
				\$6,362.15
				20.00%
				\$1,272.43
				DISCOUNTED TOTAL
				\$5,089.72
1	BOOTLID ADVERTISEMENT			\$100.00
1	REAR FENDER ADVERTISEMENT LH/RH			\$200.00
1	BOOTLID COMFORT APP STICKER			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00
1	REAR NUMBER PALTE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR			\$180.00
				\$635.00
	Labour Charge			
	Panel Beating			\$900.00
	Spray Painting Charge			\$700.00
	Remove/Refix rear wscreen and lower glass			\$180.00
	Check wiring and lighting			\$60.00
	Tuff Kote			\$60.00
	Remove/Refix reverse sensor			\$60.00
	TOTAL LABOUR			\$1,960.00
	ESTIMATE TOTAL			\$7,684.72

Date/Time: 18.12.2021 11:07

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4153437

JC NO305498349

CUSTOMER

REGN NO.:

SHA9430H

MILEAGE

IR/MS CITYCAB PTE LTD

CUSTOMER NO. 7010070

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

EL. (R) 65551188

(O)

(P)

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 18.12.2021 10:46

YR OF MANU.

02.07.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164618

COMPLETION DATE/TIME:

DISCOUNT CARD NO.

JOB DESCRIPTION


Accident Date: 09.12.2021

NATURE: 3P 09.12.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

18:

No.:

Reg No.: SHA9430H

CHIANG

Vehicle No.:

SHA9430H

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard