



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

21/1/2022

Survey Details:

Date of loss	17-Dec-21
Date of appointment	20-Dec-21
Date of survey	21-Dec-21
Location of survey	YAP MOTOR REPAIR SERVICE

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SLR 9875X
Make and Model	HONDA FREED 1.5G HYBRID AUTO
Date of registration	31/8/2017
Excess	-
Market Value	\$ 75,000.00
Part Rebate	\$ 32,204.00
Nett Loss	\$ 42,796.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>4</u>
----------------------------------	-----------------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$3,000.00 - \$4,000.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	