



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2202039

INV Date 08/04/2022

Reference CC4/LPC21012882/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKL 885U
Insured Veh. YQ 2103M
Claim No. 21/21/22/VC05/025268
Policy No. Z21VC05006758
Accident Date 17/12/2021
Inspection Date 21/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21012882/Rpa3q2 Date: 08/04/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 2103M	Veh. Inspected	SKL 885U	
Policy No.	Z21VC05006758	Coverage (\$)	0.00	
Claim No.	21/21/22/VC05/025268	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	20/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER RR EVOQUE 2.0P	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	SALZA2AX6LH046197	Colour	WHITE	
Odometer	014458 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R20	PIRELLI	6 mm	
L/H Front Tyre	235/50 R20	PIRELLI	6 mm	
R/H Rear Tyre	235/50 R20	PIRELLI	6 mm	
L/H Rear Tyre	235/50 R20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2021	Inspection Date	21/12/2021	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 885U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER -FRONT (SN)	CUT	1,958.10	1,762.29
1	FENDER -FRONT RH (SN)	BENT	867.60	780.84
1	GRILLE -FENDER -FR (SN)	NECESSARY	194.30	174.87
1	MOULDING -DOOR OUTS (SN)	NECESSARY	189.60	170.64
1	INSULATOR -SOUND (SN)	NECESSARY	93.50	84.15
1	INSULATOR -FENDER A (SN)	NECESSARY	90.00	81.00
15	BUMPER NUT XF (SN)	NECESSARY	70.50	63.45
1	RH BRACKET -BUMPER (SN)	NECESSARY	28.00	25.20
1	SENSOR -PARKING AID (SN)	NOT NECESSARY	346.90	-
			3,838.50	3,142.44
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER ,FRONT FENDER RH ,FRONT FENDER FINISHER RH ,FRONT DOOR FINISHER RH, ETC REPAIR FRONT DOOR RH .		5,200.00	2,600.00
	TO SPRAY FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH ,ETC.		4,000.00	3,000.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		621.00	621.00
			9,821.00	6,221.00
GRAND TOTAL			13,659.50	9,363.44
RECOMMENDED COST OF REPAIRS				9,363.44

Report Ref No. CC4/LPC21012882/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKL 885U

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKL 885U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

