

- C00001
Mr Goh Tze Peen
638 East Coast Road

SERVICE ESTIMATE

SL: SERVICE SALES - PC

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 20/12/2021

WIP No. : 60236

Veh.In/Out:

*Tel.No. : Mobile: 96877771

Reg.No. : SKL885U

Reg.date : 09/10/2020

Mileage : 0

Chassis No: SALZA2AX6LH046197

Singapore 459024

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Goh Tze Peen

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER, @1300	0	5200.00	0		5,200.00	S
	FRONT FENDER RH, FRONT FENDER					2600	
	FINISHER RH, FRONT DOOR FINISHER RH,						
	ETC REPAIR FRONT DOOR RH						
800	TO SPRAY FRONT BUMPER, FRONT	0	4000.00	0	3000	4,000.00	S
	FENDER RH, FRONT DOOR RH, ETC @1000						
280	TO CHECK WIRING INCLUDE	0	621.00	0		621.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	/BUMPER - FRONT cut	1.0 EA	1958.10		1762.24	1,958.10	S
	/FENDER - FRONT RH bt	1.0 EA	867.60		780.84	867.60	S
	/GRILLE - FENDER - FR ne photo	1.0 EA	194.30		174.87	194.30	S
	/MOULDING - DOOR OUTS ne photo	1.0 EA	189.60		170.64	189.60	S
	/INSULATOR - SOUND - ? photo ne	1.0 EA	93.50		84.15	93.50	S
	/INSULATOR - FENDER A ? photo	1.0 EA	90.00		81.00	90.00	S
	BUMPER NUT XF ne	15.0 EA	4.70		63.45	70.50	S
	RH BRACKET - BUMPER ne	1.0 EA	28.00		25.20	28.00	S

SERVICE ESTIMATE

- C00001
 Mr Goh Tze Peen
 638 East Coast Road

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 20/12/2021

WIP No. : 60236

Veh.In/Out:

*Tel.No. : Mobile: 96877771

Reg.No. : SKL885U

Reg.date : 09/10/2020

Mileage : 0

Chassis No: SALZA2AX6LH046197

Singapore 459024

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Goh Tze Peen

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount	G
	SENSOR - PARKING AID <i>Xm</i>	1.0 EA	346.90	346.90	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul
Hp 90010068
5 days
21/12/21 @ 1530
Resy before paint

Labour Total	9,821.00
Parts Total	3,838.50
Package Total	0.00

Gross Total.	13,659.50
Net.....	13,659.50
GST @ 7.0%	956.17
Total.....	14,615.65
Paid.....	0.00
Please Pay..	14,615.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated