

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Liu Chun Cheong

Date: 05 Jul 2022

## **Preliminary Advice**

Insured Vehicle No	: SMX931H		
TP Vehicle No	: SMK5332Y	Accident Date	: 18/12/2021
Make	: HONDA ACCORD	Assignment Date	: 20/12/2021
Date of Inspection	: 21/12/2021	Est. Duration of Repair	: 10
Inspection At	: PEGASUS ENGINEERING & TRADING PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,113.54
Revised Amount	:S\$	8,176.06
Check Items (Estimated)	:S\$	
Total	:S\$	8,176.06
Lump Sum Repair	:S\$	6,550.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a "Without Prejudice" basis.  
Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.