



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

3010

Customer :

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

## QUOTATION

NO. : 39714

DATE : 23/11/2021

CLAIM NO. : 11837

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBM4882C  
MAKE/MODEL : HON / PCX150 A

(Page 1 of 2)

| S/N | Description                                                                           | Action         | Qty  | Unit Price    | Amount |
|-----|---------------------------------------------------------------------------------------|----------------|------|---------------|--------|
| 1   | BAR HANDLE / BT<br>P/N: 49593<br>- (REPORTED BY MECHANIC)                             | REPLACE        | 1.00 | \$89.00 ✓     | 89.00  |
| 2   | BOX REAR (KAPPA) K-VENTURE 42L / CT<br>P/N: 57761<br>- (REPORTED BY MECHANIC)         | REPLACE        | 1.00 | \$795.00 ✓    | 795.00 |
| 3   | COVER INNER / CT, BR<br>P/N: 71947<br>- (REPORTED BY MECHANIC)                        | REPLACE        | 1.00 | \$84.00 ✓     | 84.00  |
| 4   | COVER SIDE LOWER LH / CT<br>P/N: 71946<br>- (REPORTED BY MECHANIC)                    | REPLACE        | 1.00 | \$105.00 ✓    | 105.00 |
| 5   | COWLING FRONT LH / CT<br>P/N: 71945<br>- (REPORTED BY MECHANIC)                       | REPLACE        | 1.00 | \$182.00 ✓    | 182.00 |
| 6   | LABOUR<br>P/N: 06766<br>- LABOUR QUOTED FOR DISMANTLING AND<br>INSTALLATION OF PARTS. | Supply/Install | 8.00 | \$63.00 ✓ 360 | 504.00 |
| 7   | LEVER BRAKE RCB S1 LH / BR<br>- (REPORTED BY MECHANIC)                                | REPLACE        | 1.00 | \$105.00 ✓    | 105.00 |
| 8   | MUDGUARD FRONT / CT<br>P/N: 71944<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00 | \$98.00 ✓     | 98.00  |
| 9   | RIZOMA MIRROR END / BR<br>- (REPORTED BY MECHANIC)                                    | REPLACE        | 1.00 | \$138.00 ✓    | 138.00 |

\*39714 \*

bizSAFE<sub>3</sub>



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383  
ISO 9001: 2015

| S/N               | Description                                                | Action  | Qty  | Unit Price | Amount            |
|-------------------|------------------------------------------------------------|---------|------|------------|-------------------|
| 10                | STAND MAIN<br>P/N: 71949<br>- (REPORTED BY MECHANIC)       | REPLACE | 1.00 | \$58.00 ✓  | 58.00             |
| 11                | STAND SIDE<br>P/N: 71948<br>- (REPORTED BY MECHANIC)       | REPLACE | 1.00 | \$35.00 ✓  | 35.00             |
| 12                | STAY FRONT COVER<br>P/N: 52543<br>- (REPORTED BY MECHANIC) | REPLACE | 1.00 | \$175.00 ✓ | 175.00            |
| 13                | STEP FLOOR LH<br>P/N: 52559<br>- (REPORTED BY MECHANIC)    | REPLACE | 1.00 | \$89.00 ✓  | 89.00             |
| SUB TOTAL         |                                                            |         |      |            | \$2,457.00        |
| GST @ 7 %         |                                                            |         |      |            | \$171.99          |
| GRAND TOTAL (SGD) |                                                            |         |      |            | <b>\$2,628.99</b> |

**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of

**BAN HOCK HIN CO PTE LTD**




RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

3 Days.  
part by part.  
After my car photos.  
Gino Riap.  
8288082  
20/12/21.



\*39714 \*

bizSAFE<sub>3</sub>

