



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

3010

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

QUOTATION

NO. : 39714

DATE : 23/11/2021

CLAIM NO. : 11837

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBM4882C
MAKE/MODEL : HON / PCX150 A

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE / BT P/N: 49593 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$89.00 ✓	89.00
2	BOX REAR (KAPPA) K-VENTURE 42L / CT P/N: 57761 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$795.00 ✓	795.00
3	COVER INNER / CT, BR P/N: 71947 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00 ✓	84.00
4	COVER SIDE LOWER LH / CT P/N: 71946 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$105.00 ✓	105.00
5	COWLING FRONT LH / CT P/N: 71945 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00 ✓	182.00
6	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$63.00 ✓ 360	504.00
7	LEVER BRAKE RCB S1 LH / BR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$105.00 ✓	105.00
8	MUDGUARD FRONT / CT P/N: 71944 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$98.00 ✓	98.00
9	RIZOMA MIRROR END / BR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$138.00 ✓	138.00

*39714 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	STAND MAIN P/N: 71949 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.00 ✓	58.00
11	STAND SIDE P/N: 71948 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00 ✓	35.00
12	STAY FRONT COVER P/N: 52543 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$175.00 ✓	175.00
13	STEP FLOOR LH P/N: 52559 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$89.00 ✓	89.00
SUB TOTAL					\$2,457.00
GST @ 7 %					\$171.99
GRAND TOTAL (SGD)					\$2,628.99

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD




RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

3 Days.
part by part.
After my car photos.
Gue Ri ang.
8288082
20/12/21.



*39714 *

bizSAFE₃





QUOTATION

Customer :

NO. : **39714**

- Rev. 1

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

DATE : 23/11/2021
CLAIM NO. : 11837
POLICY NO. :

ATTN: MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBM4882C
MAKE/MODEL : HON / PCX150 A

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 49593 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$89.00 Disc %: 10.00	80.10
2	BOX REAR (KAPPA) K-VENTURE 42L P/N: 57761 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$795.00 Disc %: 10.00	715.50
3	COVER INNER P/N: 71947 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00 Disc %: 10.00	75.60
4	COVER SIDE LOWER LH P/N: 71946 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$105.00 Disc %: 10.00	94.50
5	COWLING FRONT LH P/N: 71945 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00 Disc %: 10.00	163.80
6	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$45.00	360.00
7	LEVER BRAKE RCB S1 LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$105.00 Disc %: 10.00	94.50
8	MUDGUARD FRONT P/N: 71944 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$98.00 Disc %: 10.00	88.20
9	RIZOMA MIRROR END - (REPORTED BY MECHANIC)	REPLACE	1.00	\$138.00 Disc %: 10.00	124.20

*39714 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>		<u>Amount</u>
10	STAND MAIN P/N: 71949 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.00	✓ Disc %: 10.00	52.20
11	STAND SIDE P/N: 71948 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	✓ Disc %: 10.00	31.50
12	STAY FRONT COVER P/N: 52543 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$175.00	✓ Disc %: 10.00	157.50
13	STEP FLOOR LH P/N: 52559 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$89.00	✓ Disc %: 10.00	80.10
14	GRIP HANDLE SET (GPR) F2 P/N: 45347	Replace	1.00	\$10.00	✓ Disc %: 10.00	9.00
SUB TOTAL						\$2,126.70
GST @ 7 %						\$148.87
GRAND TOTAL (SGD)						\$2,275.57

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

***39714 ***

