

REPAIR ESTIMATE

Time: 11:08:37

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305498358
 REGN NO : SHC8113U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 07.11.2019
 DATE/TIME IN : 19.12.2021 19:50
 ACCIDENT DATE : 19.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40 20.00 367.52 <i>de</i>
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00 20.00 17.60 <i>re</i>
0003	04-01-0104-0575-G	PANEL ASSY-QUARTER OUTER	1	1,768.30 20.00 1,414.64 <i>Rp</i>
0004	04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80 20.00 44.64 <i>Xnn</i>
SUB-TOTAL :				1,844.40

481.40
385.12

JOB NATURE

0000 PB	PANEL BEATING	800.00	<i>525</i>
0001 SP	SPRAYPAINT CHARGE	600.00	<i>500</i>
0002 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	120.00	<i>60</i>
0003 L	REMOVE/REFIX REVERSE SENSOR	50.00	<i>30</i>
SUB-TOTAL :		1,570.00	

1115
\$1500.12
3 days

Tanflin 97495719
wp' 20/12/21 @ 530pm
and 2-3 days
P/P Resurvey before paint
Tanflin @ khando. lewa

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: