

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

JTNB23HK203075013

Veh# : SMY8003D

Cecilia

Model:

TOYOTA CAMRY

25/3/2021

Accident Date : 19/12/2021

Location : SEMBAWANG ROAD & GAMBAS AVE JUNCTION

3P:

GBG6263H (AIG)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>De-bond</i>	1,132.40	656	
2	2pcs	Rear bumper o/s & n/s lower garnish (black) del NN	385.60	X	
3	10pcs	Rear bumper clips <i>the</i>		30.00	
4	1pc	Rear bumper enforcement <i>Perked</i>	752.60	458	
5	2pcs	Rear bumper o/s & n/s stay enforcement <i>the n</i>	330.60	X	
6	2pcs	Rear bumper o/s & n/s reflector <i>the n</i>	155.40	X	
7	2pcs	Rear bumper o/s & n/s retainer <i>the n</i>	162.70	X	
8	2pcs	Rear reverse sensor <i>the n</i>	841.20	X	
9	1 pc	Rear buzzer <i>the n</i>	387.90	X	
		Rear bumper <i>1115</i>			
		<i>836.25</i> Sub-Total:	4,148.40	30.00	0.00
			25%	0%	10%
		<i>S.N: 30</i> After Less %:	3,111.30	30.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		500.00 250	
2		To spray painting.		400.00 250	
3		To re-set electrical system.		120.00 X	
4		To check wiring.		50.00 30	
5		To re-seal anti-rust.		50.00 X	
		Sub-Total:		1,120.00	
		Total:		4,261.30	

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAC

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *[Signature]* Accredited Certification Body

Date: *[Date]* SAC

bizSAFE 8778 1999 24 hr accident call

Adrian Cij
P/P 20/12/21.
total: 1396.25 (P/P)
02hry

