



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300624

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 02/02/2023
Reference CC6/CTI21012912/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 1839R
Insured Veh. SGV 6715H
Claim No. SNM21D207415/C02
Policy No. DMPCSNW00074862100
Accident Date 18/12/2021
Inspection Date 22/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21012912/Dpa3q2 Date: 02/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGV 6715H	Veh. Inspected	SHA 1839R	
Policy No.	DMPCSNW00074862100	Coverage (\$)	0.00	
Claim No.	SNM21D207415/C02	Excess (\$)	0.00	
Assign From		Assign Date	22/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU095300	Colour	BLUE	
Odometer	494069 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S CENTRE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/12/2021	Inspection Date	22/12/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1839R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	2,171.40	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	51.80	-
1	REAR DOOR (RH)	DENTED	2,201.10	2,201.10
1	REAR DOOR RUBBER (RH)	NECESSARY	280.50	280.50
1	ROCKER PANEL OUTER GARNISH (RH)	CUT	732.80	732.80
1	ROCKER PANEL OUTER GARNISH CLIPS	SERVICEABLE	65.00	-
1	FRONT BUMPER COVER	DENTED / BROKEN	1,052.20	1,052.20
1	FRONT BUMPER GRILLE (RH)	NOT NECESSARY	149.20	-
1	FRONT BUMPER LIP	NOT NECESSARY	152.00	-
1	FRONT BUMPER BRACKET TOP (RH)	NOT NECESSARY	44.80	-
1	FRONT BUMPER BRACKET (RH)	BENT	49.20	49.20
1	FRONT BUMPER RETAINER MOUNTING RH	NOT NECESSARY	76.20	-
1	FRONT BUMPER GRILLE AIR DUCT (RH)	NOT NECESSARY	126.20	-
1	WIPER CONTAINER ASSY RH	DEFORMED	281.60	281.60
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (RH)	BROKEN	2,776.00	1,388.00
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	FRONT FENDER (RH)	DENTED	663.00	663.00
1	FRONT FENDER APRON PANEL (RH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (RH)	DEFORMED	174.90	174.90
1	FRONT DOOR MIRROR SIDE GARNISH	NOT NECESSARY	225.00	-
1	FRONT DOOR BLACK PLASTIC COVER	NECESSARY	84.20	84.20
1	FRONT DOOR MIRROR ASSY (RH)	NOT NECESSARY	893.50	-
1	FRONT DOOR (RH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR RUBBER	NECESSARY	290.50	290.50
1	FRONT DOOR HINGE UPPER (RH)	NOT NECESSARY	113.60	-
1	FRONT DOOR HINGE LOWER (RH)	NOT NECESSARY	125.70	-
1	FRONT DOOR CHECK (RH)	NOT NECESSARY	91.80	-
1	FRONT DOOR TRIM BOARD (RH)	NOT NECESSARY	997.40	-
1	FRONT DOOR OUTER HANDLE (RH)	NOT NECESSARY	132.30	-

Report Ref No. CC6/CTI21012912/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL RIM (RH)	DISTORTED	650.60	325.30
1	FRONT WHEEL HUB CAP (RH)	CUT	214.20	107.10
1	KNUCKLE ARM (RH)	DISTORTED	1,104.00	552.00
1	FRONT WHEEL BEARING AND HUB (RH)	DAMAGED	863.80	301.80
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	595.90	529.30
1	FRONT SHOCK ABSORBER ASSY (RH)	DISTORTED	684.40	342.20
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	217.60	-
1	STG TIE ROD (RH)	NOT NECESSARY	186.40	-
1	STG TIE END (RH)	NOT NECESSARY	125.20	-
1	STABILIZER BAR ASSY	NOT NECESSARY	463.70	-
1	STABILIZER BAR LINK (RH)	NOT NECESSARY	85.90	-
1	ABS SENSOR	NOT NECESSARY	217.90	-
1	FRONT DRIVE SHAFT (RH)	NOT NECESSARY	2,061.60	-
1	RACK & PINION ASSY	NOT NECESSARY	1,820.00	-
1	BONNET (ADDITIONAL)	BENT	2,265.90	2,265.90
	LESS 20% DISCOUNT		-5,916.48	-3,084.48
			23,665.92	12,337.92
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	REAR DOOR TEL NO. STICKER (RH) (SN)	NECESSARY	10.00	10.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (RH) (SN)	NOT NECESSARY	216.00	-
			427.00	165.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER (RH).		1,800.00	800.00
	SPRAY PAINTING CHARGE.		1,800.00	1,000.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	NOT NECESSARY	150.00	-

Report Ref No. CC6/CTI21012912/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE / REFIX EXHAUST PIPE	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR MECHANISM FRONT.		80.00	60.00
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	TRANSFER OF DOOR MECHANISM REAR.		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE / REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	RE-SET FRT ABS SYSTEM.	NOT NECESSARY	200.00	-
	REMOVE / REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE / REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-
	REMOVE / REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			6,740.00	2,350.00
GRAND TOTAL			30,832.92	14,852.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,800.00

Report Ref No. CC6/CTI21012912/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1839R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1839R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1839R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

