

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 20-Dec-21
 MODEL: HYUNDAI I40
 VEHICLE NO.: SHA 1839R
 INSURANCE: China Taiping

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR FENDER (RH) <i>dam</i>	1	\$ 2,171.40	\$2,171.40	X
REAR WINDSCREEN MOULDING HH	1	\$ 51.80	\$51.80	X
REAR DOOR (RH) <i>dent</i>	1	\$ 2,201.10	\$2,201.10	✓
REAR DOOR RUBBER (RH) <i>hec</i>	1	\$ 280.50	\$280.50	✓
ROCKER PANEL OUTER GARNISH (RH) <i>& cut</i>	1	\$ 732.80	\$732.80	✓
ROCKER PANEL OUTER GARNISH CLIPS <i>sn</i>	1	\$ 65.00	\$65.00	X
FRONT BUMPER COVER <i>Dented / broken</i>	1	\$ 1,052.20	\$1,052.20	✓
FRONT BUMPER GRILLE (RH) HH	1	\$ 149.20	\$149.20	X
FRONT BUMPER LIP HH	1	\$ 152.00	\$152.00	X
FRONT BUMPER BRACKET TOP (RH) HH	1	\$ 44.80	\$44.80	X
FRONT BUMPER BRACKET (RH) <i>bt</i>	1	\$ 49.20	\$49.20	✓
FRONT BUMPER RETAINER MOUNTING RH HH	1	\$ 76.20	\$76.20	X
FRONT BUMPER GRILLE AIR DUCT (RH) HH	1	\$ 126.20	\$126.20	X
WIPER CONTAINER ASSY RH <i>& deformed</i>	1	\$ 281.60	\$281.60	✓
HEADLAMP SUPPORT PANEL ASSY <i>broken</i>	1	\$ 907.40	\$907.40	✓
HEADLAMP (RH) <i>broken</i>	1	\$ 2,776.00	\$2,776.00	✓ 1388.00
HEADLAMP SUPPORT TOP COVER HH	1	\$ 222.60	\$222.60	X
FRONT FENDER (RH) <i>Dented</i>	1	\$ 663.00	\$663.00	✓
FRONT FENDER APRON PANEL (RH) <i>Dented</i>	1	\$ 637.00	\$637.00	✓
FRONT FENDER SHIELD (RH) <i>deformed</i>	1	\$ 174.90	\$174.90	✓
FRONT DOOR MIRROR SIDE GARNISH HH	1	\$ 225.00	\$225.00	X
FRONT DOOR BLACK PLASTIC COVER <i>hec</i>	1	\$ 84.20	\$84.20	✓
FRONT DOOR MIRROR ASSY (RH) HH	1	\$ 893.50	\$893.50	X
FRONT DOOR (RH) <i>Dented</i>	1	\$ 2,256.40	\$2,256.40	✓
FRONT DOOR RUBBER <i>hec</i>	1	\$ 290.50	\$290.50	✓
FRONT DOOR HINGE UPPER (RH) HH	1	\$ 113.60	\$113.60	X
FRONT DOOR HINGE LOWER (RH) HH	1	\$ 125.70	\$125.70	X
FRONT DOOR CHECK (RH) HH	1	\$ 91.80	\$91.80	X
FRONT DOOR TRIM BOARD (RH) HH	1	\$ 997.40	\$997.40	X
FRONT DOOR OUTER HANDLE (RH) HH	1	\$ 132.30	\$132.30	X
FRONT WHEEL RIM (RH) <i>& distorted</i>	1	\$ 650.60	\$650.60	✓ 325.30
FRONT WHEEL HUB CAP (RH) <i>cut</i>	1	\$ 214.20	\$214.20	✓ 107.10
KNUCKLE ARM (RH) <i>& distorted</i>	1	\$ 1,104.00	\$1,104.00	✓ 552.00
FRONT WHEEL BEARING AND HUB (RH) <i>& Down</i>	1	\$ 863.80	\$863.80	✓ 301.80
FRONT SUSPENSION LOWER ARM (RH) <i>& distorted</i>	1	\$ 595.90	\$595.90	✓ 529.30
FRONT SHOCK ABSORBER ASSY (RH) <i>& distorted</i>	1	\$ 684.40	\$684.40	✓ 342.20
FRONT SHOCK ABSORBER MOUNTING (RH) HH	1	\$ 217.60	\$217.60	✓
STG TIE ROD (RH) HH	1	\$ 186.40	\$186.40	X
STG TIE END (RH) HH	1	\$ 125.20	\$125.20	✓
STABILIZER BAR ASSY HH	1	\$ 463.70	\$463.70	X
STABILIZER BAR LINK (RH) HH	1	\$ 85.90	\$85.90	✓
ABS SENSOR HH	1	\$ 217.90	\$217.90	✓
FRONT DRIVE SHAFT (RH) HH	1	\$ 2,061.60	\$2,061.60	X

RACK & PINION ASSY HH	1	\$ 1,820.00	\$1,820.00	X
SUB TOTAL			\$27,316.50	
LESS 20%			\$5,463.30	
DISCOUNTED TOTAL			\$21,853.20	
REAR WINDSCREEN SEALANT HH SN	1	\$ 46.00	\$46.00	X
REAR DOOR TEL NO. STICKER (RH) Hec SN	1	\$ 10.00	\$10.00	✓
Rear Door Comfortdelgro & Apps Sticker(RH) Hec SN	1	\$ 80.00	\$ 80.00	✓
FRONT DOOR COMFORT LOGO (RH) Hec SN	1	\$ 75.00	\$75.00	✓
FRONT TYRE (RH) HH SN	1	\$ 216.00	\$216.00	X
SUB TOTAL			\$427.00	
Labour Charge				
Panel Beating	1	\$ 1,800.00	\$1,800.00	800/-
Spray Painting Charge	1	\$ 1,800.00	\$1,800.00	800/-
Wiring Charge	1	\$ 100.00	\$100.00	1000/-
Tuff Kote	1	\$ 100.00	\$100.00	40/- 30/-
Towing Charge	1	\$ 80.00	\$80.00	40/-
Remove/Refix Cushion & Upholstery Rear	1	\$ 150.00	\$150.00	HH
Remove/Refix Rear Windscreen Glass	1	\$ 120.00	\$120.00	HH
Remove/Refix Reverse Sensor	1	\$ 120.00	\$120.00	HH
Remove/Refix Fuel Tank	1	\$ 150.00	\$150.00	HH
Remove/Refix Exhaust Pipe	1	\$ 150.00	\$150.00	HH
Transfer of Door Mechanism FRONT	1	\$ 80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$ 200.00	\$200.00	HH
Transfer of Door Mechanism REAR	1	\$ 80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$ 200.00	\$200.00	HH
Four Wheel Alignment	1	\$ 120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$ 400.00	\$400.00	150/-
Re-set Frt ABS System	1	\$ 200.00	\$200.00	HH
Remove/Refix Radiator	1	\$ 90.00	\$90.00	HH
Remove/Refix Aircon & Refill Gas	1	\$ 130.00	\$130.00	HH
Remove/Refix Fuse Box	1	\$ 120.00	\$120.00	HH
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00	150/-
TOTAL LABOUR			\$6,740.00	
ESTIMATE TOTAL			\$ 29,020.20	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance				

13156.50

10525.20

165.00

800/-

800/-

1000/-

40/- 30/-

40/-

HH

HH

HH

HH

HH

60/-

HH

60/-

HH

60/-

HH

HH

HH

150/-

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

22/12/2021 @ 0930h

Not Author

1/2 year 78 days.

1 year

2kk And

13040.20

Supp 1812.72

14,852.92

45 11,800/-

Check 74A prices.

Check BV

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 22-Dec-21 INSURANCE: Chine Teiping
MODEL: HYUNDAI I40
VEHICLE NO.: SHA 1839R

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET 碎	1	\$ 2,265.90	\$2,265.90
SUB TOTAL			\$2,265.90
LESS 20%			\$453.18
DISCOUNTED TOTAL			\$1,812.72
ESTIMATE TOTAL			\$1,812.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

Inja

2kk ADU

8