COMFORT TRANSPORTATION PTE LTD REPAIR ESTIMATE

Vehicle No. : SHD6726J

Make

: HYUNDAI

Model

: IONIQ(G2)

Date: 20/12/2021

Insurance: AIG

MVA: MS. LOKE YY

Parts Description / Labour	Туре	Unit Price	Amount
REAR BUMPER COVER			\$459.
N. SALES FOR			\$22
A Proceedings of the Control of the			\$451
REAR BUMPER REINFORCEMENT			\$394
REAR BUMPER LOWER CTR MOULDING			\$155
			\$40
			\$201
LICENCE LAMP			\$85
SUBT	OTAL		\$1,482
			\$296
			\$1,185
1 REAR NUMBER PLATE WITH TRIM COVER 1 REAR BUMPER REVERSE SENSOR			\$55 \$180 \$235
Labour Charge			350 \$400
			250 \$300
			× \$60
			30 \$80
Programma Construction (Construction Construction Constru	BOUR		\$840
ESTIMATE 1	OTAL		\$2,260
1 1 1	REAR BUMPER COVER REAR BUMPER CLIPS REAR BUMPER CENTRE MOULDING ASSY REAR BUMPER REINFORCEMENT REAR BUMPER LOWER CTR MOULDING ANTENNA SMARTKEY REAR BUMPER FOG LAMP LICENCE LAMP SUB T LESS DISCOUNTED T REAR NUMBER PLATE WITH TRIM COVER REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE CHECK ALL LIGHTING REMOVE/REFIX REVERSE SENSOR TOTAL LAI	REAR BUMPER COVER REAR BUMPER CLIPS REAR BUMPER CENTRE MOULDING ASSY REAR BUMPER REINFORCEMENT REAR BUMPER LOWER CTR MOULDING ANTENNA SMARTKEY REAR BUMPER FOG LAMP LICENCE LAMP SUB TOTAL LESS 20% DISCOUNTED TOTAL REAR NUMBER PLATE WITH TRIM COVER REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE CHECK ALL LIGHTING	REAR BUMPER COVER REAR BUMPER CLIPS REAR BUMPER CENTRE MOULDING ASSY REAR BUMPER CENTRE MOULDING ASSY REAR BUMPER LOWER CTR MOULDING ANTENNA SMARTKEY REAR BUMPER FOG LAMP LICENCE LAMP SUB TOTAL LESS 20% DISCOUNTED TOTAL REAR NUMBER PLATE WITH TRIM COVER REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE CHECK ALL LIGHTING REMOVE/REFIX REVERSE SENSOR

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Touthin 97495749

W 20/12/21 (530)

Plessey newports

fughth Clubanto com

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:



ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainthie + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508989
383 Sin Ming Drive Singapore 575717
20.12.2021 15:53 Page: 1

The second secon	IOR CARD	gal.	es Order: 415365	A	JC NO305498603
Team: ARC Repair TP(CLSO)1	JOB CAND	Sal		.Z.	MILEAGE
STOMER COMFORT TRANSPORTATION PTE	T.TD		REGN NO.: SHD6726J		505
7010045	HID		MAKE: HYUNDAI		FUEL EF
DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717			MODEL IONIQ(G3)	20.	12.2021 14:35
L. (R) 65508755 (O)			YR OF MANU. 30.10.2020		TARGET DATE
(P)	5.		CHASSIS CODE KMHC851CVLUI	01624	COMPLETION DATE/TIME:
SCOUNT CARD NO.			KMHC82TCATO	31024	
Accident Date: 20.12.2021 NATURE: 3P 20.12.2021	JOB DESCRIPTION				
S/NO LABOR CODE	DESC	RIP	TION	-15-	FRONT
			я	The state of the s	
	~				
				A F	
			LEFT SIDE		HI SIDE
			DE L		
				REAR L	
HECKED & PASSED OUT BY:					
SERVICE ADVISOR			CU	STOMER'S	SIGNATURE
rowledgement Slip	Exit Pass				
owiedgement Silp	LAN POSS				
e: lo.:	Vehicle No.:	CITT	6726 T		
sle No.: SHD6726J YY		SHU	67.26J		
e of Service Advisor Signature/Da	te Name of Servi	ice Advi	sor E	Date	
Freturned to Service Reception upon collection	To be kept by	Securit	Guard		
					,