

FORT TRANSPORTATION PTE LTD

AIR ESTIMATE

Vehicle No. : SHD6726J

Date: 20/12/2021

Make : HYUNDAI

Insurance: AIG

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			tnv ✓ \$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	ANTENNA SMARTKEY			coe ✓ \$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
	SUB TOTAL		973.15	\$1,482.45
	LESS 20%			\$296.49
	DISCOUNTED TOTAL		778.52	\$1,185.96
1	REAR NUMBER PLATE WITH TRIM COVER			ava ✓ \$55.00
1	REAR BUMPER REVERSE SENSOR		235	nw ✓ \$180.00
				\$235.00
	Labour Charge			
	PANEL BEATING			350 \$400.00
	SPRAY PAINTING CHARGE			250 \$300.00
	CHECK ALL LIGHTING			nax \$60.00
	REMOVE/REFIX REVERSE SENSOR		630	30 \$80.00
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL		\$1643.52	\$2,260.96
			> 2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Paypin 97495747
 up 20/12/21 0530

2 days
 e/p Resurvey new parts
 Paypin 97495747

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and