

TPAXA.

SMU 6918Z. 2020 August.

VERON.

Toyota Camry Hybrid. 2487cc.

JTNB23HK003065886

Rees Bumper	2hd	655.90 ✓
Rees Bumper Clips.	nr	30(SN). ✓
Rees Bumper Side Holder x 02	x4 nr	$168.4 \times 2 = 336.80$ X
Rees Bumper Side Reflector LH.	M 2	189.10. X
Rees Bumper Reinforcement.	Dented	382.70. ✓

Reverse Sensor	ALL nr	255. X
----------------	--------	--------

Rees End Panel.	Ryir	786.40. X.
-----------------	------	------------

Trunk LH.	Crushed	568.70 ✓
-----------	---------	----------

Bootlid	Ryir	987.10. X
---------	------	-----------

Bootlid Lock	2	580.70. X
--------------	---	-----------

Bootlid Weatherstripe.	NP nr	390.90. X
------------------------	----------	-----------

Toyota Logo.	2	98.70. ✓
--------------	---	----------

Hybrid Emblem.	nr	75.60 ✓
----------------	----	---------

Spere Tyre Panel Undercover	NP nr	382.10 X
-----------------------------	----------	----------

Spere Tyre Panel Undercover Clips	NP nr	30(SN) X
-----------------------------------	----------	----------

SMU 69/82

Panel Beating.

~~800~~ 500

Spray Painting.

~~800~~ 600

Wiring.

~~50~~ 30

To spray tuff coat

~~150~~ 40

To remove remove sensor

~~100~~ 50

To remove upholstery.

~~150~~ 40.

hist: 1781.60

Labour: 1260

less 25%: 1336.20.

total: 2626.20

S.N: 30

L/S: 2.1K.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: