

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
KIRAN PAL SINGH	Cust No/Name LCV12069/KIRAN PAL SINGH
72 MARINE DRIVE	Reg No/Reg Date SKX169R / 19/02/202
#19-65	Date In/Mileage / 0
SINGAPORE 440072	Chassis No KNAE351AML6080066
Contact No	Engine No G4KLKH027498
	Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV12069	CRDVCH	20/12/2021/ 16:54	BLC	442 / CocoLu	44208			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								20.00
Sundry								
E PNT88000								1600.00
RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR BONNET, FRT FENDER RH					1.5	400		
E PNT88000								100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								80.00
TOP UP AIRCON GAS								
E PNT98000								1050.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH					3	350		
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								20.00
FRT NUMBER PLATE FRAME								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								1160.00
SUPPLY FRT LEFT TYRE AND REAR LEFT TYRE								
M SUNDRY								60.00
TRANSFER FRT & REAR LEFT TYRE								
A 90000001								400.00
RENEW FRT DASHBOARD AND AIRBAG SYSTEM								
A 90000001								400.00
RENEW FRT & BACK SEAT BELTS & IMPACT SENSOR								
E PNT88000								240.00
RENEW FRT WINDSCREEN								
M SUNDRY								80.00
APPLY SEALANT FOR FRT WINDSCREEN								
S SPECIALISTJOB								240.00
RENEW FRT WINDSCREEN SOLAR FILM								
M COVER-FR BUMPER					1.00	646.00	00.00	646.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
KIRAN PAL SINGH	Cust No/Name LCV12069/KIRAN PAL SINGH
72 MARINE DRIVE	Reg No/Reg Date SKX169R / 19/02/202
#19-65	Date In/Mileage / 0
SINGAPORE 440072	Chassis No KNAE351AML6080066
Contact No	Engine No G4KLKH027498
	Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV12069	CRDVCH	20/12/2021/ 16:54	BLC	442 / CocoLu	44208
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M LOGO ASSY-KIA SUB <i>nc</i>	1.00	45.00	00.00	45.00	
M GRILLE-FRONT BUMPER <i>cut</i>	1.00	391.00	00.00	391.00	
M GRILLE ASSY-RADIATOR <i>cut</i>	1.00	444.00	00.00	444.00	
M ABSORBER-FRONT BUMPER ENERGY	1.00	105.00	00.00	105.00	
M COVER ASSY-AIR CURTAIN,RH	1.00	126.00	00.00	126.00	
M BRACKET-FR BUMPER SIDE SUPT,RH <i>work</i>	1.00	18.00	00.00	18.00	
M LIP ASSY-FRONT BUMPER <i>cut</i>	1.00	22.00	00.00	22.00	
M MOULDING-FRT BPR LICENSE PLATE <i>CRU</i>	1.00	35.00	00.00	35.00	
M CAP-FRONT HOOK <i>CRU</i>	1.00	9.00	00.00	9.00	
M COVER ASSY-RADIATOR GRILLE UP	1.00	72.00	00.00	72.00	
M COVER ASSY-FENDER SIDE,RH	1.00	13.00	00.00	13.00	
M STIFFNER-FR BPR LWR	1.00	127.00	00.00	127.00	
M BRACKET-FRT BUMPER MOUNTING,RH	1.00	10.00	00.00	10.00	
M BRKT ASSY-FRT BUMPER SIDE MTG	1.00	15.00	00.00	15.00	
M BRACKET-FR BUMPER SIDE,LH	1.00	15.00	00.00	15.00	
M ULTRASONIC SENSOR ASSY-BWS	1.00	189.00	00.00	189.00	
M GUARD ASSY-FRONT WHEEL,RH	1.00	159.00	00.00	159.00	
M BEAM COMPLETE-FR BUMPER	1.00	620.00	00.00	620.00	
M CARRIER ASSY-FRONT END MODULE	1.00	697.00	00.00	697.00	
M TENSION ARM ASSY-FRT,RH	1.00	644.00	00.00	644.00	
M LATERAL ARM ASSY-FRONT	1.00	535.00	00.00	535.00	
M COVER ASSY-COWL TOP	1.00	216.00	00.00	216.00	
M GLASS ASSY-WINDSHIELD <i>RR</i>	1.00	2009.00	00.00	2009.00	
M MOULDING-WINDSHIELD GLASS <i>nc</i>	1.00	92.00	00.00	92.00	
M MOULDING ASSY-W/SHLD SIDE,RH <i>nc</i>	1.00	94.00	00.00	94.00	
M MOULDING ASSY-W/SHLD SIDE,LH <i>nc</i>	1.00	94.00	00.00	94.00	
M BRACKET-W/S MLDG MTG,RH <i>nc</i>	1.00	27.00	00.00	27.00	
M BRACKET-W/S MLDG MTG,LH <i>nc</i>	1.00	27.00	00.00	27.00	
M LAMP ASSY-HEAD,RH <i>cut</i>	1.00	3977.00	00.00	3977.00	
M EXTN WIRING ASSY-SPAS	1.00	194.00	00.00	194.00	
M WIRING ASSY-FEM	1.00	256.00	00.00	256.00	
M SENSOR ASSY-A TYPE CRASH <i>nc</i>	2.00	96.00	00.00	192.00	
M MODULE ASSY-AIR BAG CONTROL <i>nc</i>	1.00	810.00	00.00	810.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
KIRAN PAL SINGH	Cust No/Name LCV12069/KIRAN PAL SINGH
72 MARINE DRIVE	Reg No/Reg Date SKX169R / 19/02/202
#19-65	Date In/Mileage / 0
SINGAPORE 440072	Chassis No KNAE351AML6080066
Contact No	Engine No G4KLKH027498
	Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV12069	CRDVCH	20/12/2021/ 16:54	BLC	442 / CocoLu	44208

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SENSOR ASSY-PRESS TYPE CRASH <i>acc</i>	2.00	115.00	00.00	230.00
M MODULE ASSY-KNEE AIR BAG <i>GR</i>	1.00	595.00	00.00	595.00
M AIR BAG ASSY-PASSENGER <i>GR</i>	1.00	1163.00	00.00	1163.00
M MODULE ASSY-STRG WHEEL AIR BAG <i>GR</i>	1.00	1516.00	00.00	1516.00
M SENSOR-ANGULAR VELOCITY <i>acc</i>	1.00	375.00	00.00	375.00
M CONTACT ASSY-CLOCK SPRING <i>acc</i>	1.00	169.00	00.00	169.00
M CRASH PAD ASSY-MAIN <i>GR</i>	1.00	2146.00	00.00	2146.00
M PAD-CRASH PAD MAIN	1.00	15.00	00.00	15.00
M GUARD-AIR	1.00	88.00	00.00	88.00
M COOLER ASSY-OIL	1.00	391.00	00.00	391.00
M VALVE-BYPASS	1.00	205.00	00.00	205.00
M TUBE ASSY-OIL COOLER	1.00	307.00	00.00	307.00
M CONDENSER ASSY-COOLER	1.00	805.00	00.00	805.00
M RADIATOR ASSY	1.00	699.00	00.00	699.00
M SENSOR & UNIT ASSY-ACTIVE HOOD	1.00	936.00	00.00	936.00
M LATCH ASSY-HOOD	1.00	114.00	00.00	114.00
M STRIP ASSY-HOOD SEAL	1.00	25.00	00.00	25.00
M S/BELT ASSY-FR RH <i>changed</i>	1.00	420.00	00.00	420.00
M S/BELT ASSY-FR LH <i>changed</i>	1.00	420.00	00.00	420.00
M SEAT BELT PRETENSIONER, RH <i>acc</i>	1.00	194.00	00.00	194.00
M SEAT BELT PRETENSIONER, LH <i>acc</i>	1.00	194.00	00.00	194.00
M S/BELT ASSY-RR, RH <i>changed</i>	1.00	398.00	00.00	398.00
M S/BELT ASSY-RR, LH <i>changed</i>	1.00	398.00	00.00	398.00
M BRACKET, IU ADHESIVE <i>acc</i>	1.00	26.00	00.00	26.00

Estimate

Steve (LKK)

20/12/21, 5:30pm

OD- M AL

Excess-?

P/P

My BL by
10 days

LKK Auto Consultants hence notify
 Confirm & accepted by:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

7% GST on	Nett 30474.00	30,474.00
		2133.18
	Total Payable	32,607.18

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.